



report date: 2024-03-29

General information

Make	KIA
Model	SEDONA CRDI SE+
Colour	Black
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	16.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	143 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	33.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-28
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history****MOT #22** 2022-08-25 13:21**MOT test number** 697577014783**Result** ✓ Passed**Next expiry date** 2023-08-24

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Passenger seat(s) missing at time of test
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21 2022-08-25 11:19**MOT test number** 243897974548**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Passenger seat(s) missing at time of test

MOT #20 2021-07-06 15:11**MOT test number** 758442372112**Result** ✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases centre (6.1.2 (a))

**MOT #19**

2021-07-06 15:11

MOT test number

412606834868

Result**✗ Failed****Pass with rectification**

Rear fog lamp not working (4.5.1 (a) (ii))

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Exhaust has a minor leak of exhaust gases centre (6.1.2 (a))

MOT #18

2019-12-19 13:33

MOT test number

993250278151

Result**✓ Passed****MOT #17**

2019-12-18 09:11

MOT test number

581819063375

Result**✗ Failed****Advice**

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail

Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail

Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #16

2019-07-08 15:59

MOT test number

943281027635

Result**✓ Passed****Advice**

Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2018-07-09 15:18**MOT test number** 208049124871**Result** ✓ Passed**MOT #14** 2018-07-09 14:01**MOT test number** 241405016210**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Exhaust has a major leak of exhaust gases back box. (6.1.2 (a))**MOT #13** 2017-07-10 15:26**MOT test number** 949447910658**Result** ✓ Passed**MOT #12** 2016-07-11 16:25**MOT test number** 179246990294**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2015-07-06 18:06**MOT test number** 257777485110**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #10**

2015-07-06 18:06

MOT test number

218577485445

Result**✗ Failed****Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9**

2014-07-10 14:38

MOT test number

946951894104

Result**✓ Passed****MOT #8**

2014-07-10 10:37

MOT test number

365251294148

Result**✗ Failed****Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #7**

2013-07-11 15:42

MOT test number

868532493187

Result**✓ Passed**

**MOT #6** 2013-07-10 12:16**MOT test number** 305461293146**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear parking (secondary) brakes imbalanced (3.7.B.6b)**Notice** Cut in sidewall of nsf tyre**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #5** 2012-06-07 12:45**MOT test number** 749069352131**Result** ✓ Passed**MOT #4** 2011-07-14 12:53**MOT test number** 288705791450**Result** ✓ Passed**MOT #3** 2010-09-03 11:58**MOT test number** 354276240405**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-10-07 14:43**MOT test number** 892270189262**Result** ✓ Passed**MOT #1** 2008-11-05 13:03**MOT test number** 730190818300**Result** ✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-11-10
Last registration	2022-08-25
Complete history	See info



Registration #1	2005-11-10	8 mi
Registration #2	2008-11-05	21.969 mi
Registration #3	2009-10-07	28.464 mi
Registration #4	2010-09-03	35.339 mi
Registration #5	2011-07-14	41.249 mi
Registration #6	2012-06-07	48.484 mi
Registration #7	2013-07-10	53.725 mi
Registration #8	2013-07-11	53.737 mi
Registration #9	2014-07-10	64.732 mi
Registration #10	2014-07-10	64.732 mi
Registration #11	2015-07-06	76.595 mi
Registration #12	2016-07-11	80.835 mi
Registration #13	2016-07-11	80.835 mi
Registration #14	2016-07-11	80.835 mi
Registration #15	2016-07-11	80.835 mi
Registration #16	2016-07-11	80.835 mi
Registration #17	2016-07-11	80.835 mi
Registration #18	2016-07-11	80.835 mi
Registration #19	2016-07-11	80.835 mi
Registration #20	2016-07-11	80.835 mi
Registration #21	2016-07-11	80.835 mi
Registration #22	2016-07-11	80.835 mi
Registration #23	2016-07-11	80.835 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1900 mm
Height	1805 mm
Length	4925 mm
Wheel base	2905 mm
Kerb weight	2230 kg
Max. allowed weight	2748 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3703587