



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 MILLESIM
Colour	Black
Year of manufacture	2010
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	106 g/km
CO2 label	B





MOT history

MOT expiry date	2025-03-07
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	29
Total items failed	14

MOT #17	2024-03-08 14:32
MOT test number	209600612035
Result	✓ Passed
Next expiry date	2025-03-07
Advice	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16**

2024-03-08 11:29

**MOT test number**

787443933167

**Result**

✗ Failed

**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**MOT #15**

2023-02-17 16:02

**MOT test number**

703388582550

**Result**

✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #14**

2023-02-17 16:02

**MOT test number**

254335650106

**Result**

✗ Failed

**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #13** 2022-02-07 14:07**MOT test number** 342777384801**Result** ✓ Passed**MOT #12** 2022-02-04 17:40**MOT test number** 440434285383**Result** ✗ Failed

- Fail** Emissions not tested (8.2.2.2 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect bulb not fitted correctly (4.1.2 (c))
- Fail** Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Rear Stop lamp(s) not working offside and nearside (4.3.1 (a) (ii))

**MOT #11** 2021-02-15 17:26**MOT test number** 509422700061**Result** ✓ Passed

- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10** 2020-01-13 10:38**MOT test number** 609782214603**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2019-01-17 11:32**MOT test number** 634921502446**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front worn on outer edge**MOT #8** 2018-01-13 13:32**MOT test number** 765063059687**Result** ✓ Passed**MOT #7** 2018-01-13 11:00**MOT test number** 203164675613**Result** ✗ Failed**Fail** Offside Brake pipe excessively corroded Front to rear (3.6.B.2c)**MOT #6** 2017-01-21 12:59**MOT test number** 119210225050**Result** ✓ Passed**MOT #5** 2016-01-12 10:48**MOT test number** 841809566612**Result** ✓ Passed**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2016-01-12 09:35**MOT test number** 244289357826**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2015-01-19 11:50**MOT test number** 156339315475**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-01-29 14:37**MOT test number** 679769324025**Result** ✓ Passed**Notice** Oil leak**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-01-22 10:29**MOT test number** 906322223072**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
7 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	7 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-01-28
Last registration	2024-03-08
Complete history	<a href="#">See info</a>



Registration #1	2010-01-28	26 mi
Registration #2	2013-01-22	31.252 mi
Registration #3	2014-01-29	41.043 mi
Registration #4	2015-01-19	50.904 mi
Registration #5	2016-01-12	59.746 mi
Registration #6	2016-01-12	59.746 mi
Registration #7	2017-01-21	64.759 mi
Registration #8	2018-01-13	73.122 mi
Registration #9	2018-01-13	73.122 mi
Registration #10	2019-01-28	73.122 mi
Registration #11	2019-01-28	73.122 mi
Registration #12	2019-01-28	73.122 mi
Registration #13	2019-01-28	73.122 mi
Registration #14	2019-01-28	73.122 mi
Registration #15	2019-01-28	73.122 mi
Registration #16	2019-01-28	73.122 mi
Registration #17	2019-01-28	73.122 mi
Registration #18	2019-01-28	73.122 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	6589212
---------------	---------