



General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-15
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-23
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	43
Total items failed	1

MOT #15	2023-08-24 16:56
MOT test number	112295470577
Result	✓ Passed
Next expiry date	2024-08-23
Advice	Nearside Rear Inner Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))

MOT #14	2023-08-22 15:55
MOT test number	704250984670
Result	✗ Failed
MAJOR	Parking brake lever ratchet mechanism worn to the extent that the brake may inadvertently release (1.1.6 (b) (ii))
Advice	Nearside Rear Inner Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))
MAJOR	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13	2022-08-18 15:01
MOT test number	668110275183
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2022-08-18 10:58

MOT test number

910655257668

Result**✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #11

2021-08-24 16:13

MOT test number

563820555405

Result**✓ Passed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2021-07-28 14:56**MOT test number** 562706751481**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #9** 2020-06-30 15:40**MOT test number** 333377445807**Result** ✓ Passed**MOT #8** 2020-06-30 15:40**MOT test number** 836979940964**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))**MOT #7** 2019-07-05 07:26**MOT test number** 244613698876**Result** ✓ Passed

**MOT #6** 2018-07-10 14:10**MOT test number** 595012397904**Result** ✓ Passed**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #5** 2017-06-30 14:35**MOT test number** 430243576866**Result** ✓ Passed**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #4**

2016-07-04 11:05

MOT test number

262811514275

Result

✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #3

2015-06-22 13:49

MOT test number

808893575140

Result

✓ Passed

- Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #2

2014-06-30 12:55

MOT test number

385841784187

Result

✓ Passed

- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Offside front tyre wearing on inner edge



MOT #1	2013-07-09 10:53
MOT test number	967780793107
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
23 August 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RV10JRX
Plate since	2019-06-29
Current registration	 RV10JRX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-13
Last registration	2023-08-24
Complete history	See info



Registration #1	2010-07-13	16 mi
Registration #2	2013-07-09	34.046 mi
Registration #3	2014-06-30	39.093 mi
Registration #4	2015-06-22	42.353 mi
Registration #5	2016-07-04	51.670 mi
Registration #6	2017-06-30	67.012 mi
Registration #7	2018-07-10	75.653 mi
Registration #8	2019-07-05	83.637 mi
Registration #9	2020-06-30	89.732 mi
Registration #10	2020-06-30	95.777 mi
Registration #11	2020-06-30	95.777 mi
Registration #12	2020-06-30	95.777 mi
Registration #13	2020-06-30	95.777 mi
Registration #14	2020-06-30	95.777 mi
Registration #15	2020-06-30	95.777 mi
Registration #16	2020-06-30	95.777 mi
Registration #17	2020-06-30	95.777 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 058721