





General information

Make	MAZDA
Model	CX-5 D SE-L NAV
Colour	White
Year of manufacture	2012
Top speed	126 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 1.800 rpm
Engine capacity	2.191 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	119 g/km
CO2 label	С







Internet history


Entry 2

Date

Pictures

2023-12-14

8



source: g3remarketing.co.uk

Entry 1	
Date	2021-02-01
Pictures	10
Listing price	<u>View report</u>



source: autoonline.co.uk



MOT history

MOT expiry date	2024-03-03
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	2

МОТ #9	2023-03-04 11:35
MOT test number	165071339720
Result	✓ Passed
Next expiry date	2024-03-03

МОТ #8	2023-03-01 15:46
MOT test number	821946673664
Result	🗙 Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened bo	th fronts (1.1.14 (a) (ii))
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7		2020-10-13 13:55
MOT test	number	195454038719
Result		✓ Passed
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	



F	Ν	6	2	Μ	Μ	V
	re	por	t da	te: 2	024-0)3-29

MOT #6	2020-10-13 13:55
MOT test number	516165822714
Result	× Failed
Advice Offside Front Tra	ack rod end ball joint has slight play (2.1.3 (b) (i))
Advice Nearside Front	Frack rod end ball joint has slight play (2.1.3 (b) (i))
Pass with rectification (h))	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3
MOT #5	2019-09-23 11:02
MOT test number	990896269839

Result

MOT #4	2018-09-22 08:51
MOT test number	485785947577
Result	✓ Passed

MOT #3		2017-09-26 09:19
MOT test	number	383072466764
Result		✓ Passed
Advice	Offside Rear Trailing arm has slight play in a pin/bush (2.4.G.2)	
Advice	Nearside Rear Trailing arm has slight play in a pin/bush (2.4.G.2)	

MOT #2	2016-09-09 08:43
MOT test number	479210546060
Result	✓ Passed
MOT #1	2015-09-04 13:58

MOT test number	406222155463
Result	✓ Passed

🗸 Passed



FN62MMV report date: 2024-03-29

Tax & MOT check

	✓ Taxed		Х MOT
Tax due: 1 August 2024		Expired: 3 March 2024	
Tax status			Valid until 1 August
Days left			94
MOT expiry date			3 March 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		49	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	ASMPL
Date	
Category	 AMPL
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	8775-25-27





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-09-12
Last registration	2023-03-04
Complete history	See info



Registration #1	2012-09-12	11 mi
Registration #2	2015-09-04	76.395 mi
Registration #3	2016-09-09	92.257 mi
Registration #4	2017-09-26	110.595 mi
Registration #5	2018-09-22	122.275 mi
Registration #6	2019-09-23	128.469 mi
Registration #7		11.117 mi
Registration #8		11.117 esi
Registration #9		11.777 mi
Registration #10		11.777 est
Registration #11		11.777 mi





Safety ratings

NCAP rating	****
Adult	94%
Children	87%
Pedestrian	64%
Safety systems	86%
Overall rating	86%
Video	see crash video



Dimensions & weight	
Width	1840 mm
Height	1670 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1450 kg
Max. allowed weight	2035 kg
Additional information	
Additional information Fuel tank capacity	56 I
	56 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5