



T6XXM

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V STARTLINE BMT
Colour	Silver
Year of manufacture	2016
Top speed	91 mph
0 - 100 km/h	15.4 seconds
0 - 60 mph	19.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 83 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	176 g/km
CO2 label	I







Internet history

Entry 1

Date	2021-09-11
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-04
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	20
Total items failed	0

MOT #8	2024-03-16 11:27
MOT test number	546373046767
Result	✓ Passed
Next expiry date	2025-04-04

MOT #7	2023-03-30 11:38
MOT test number	153044975156
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6**

2022-04-05 08:14

MOT test number

809520982504

Result

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Sidewall Damaged (5.2.3 (d) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))

MOT #5

2022-03-30 06:50

MOT test number

166322150132

Result

✗ Failed

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Sidewall Damaged (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure 245/45/18 (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))

MOT #4

2021-03-25 08:58

MOT test number

760424415982

Result

✓ Passed

**MOT #3** 2021-03-16 14:20**MOT test number** 145635414355**Result** ✗ Failed**MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #2** 2020-03-18 17:05**MOT test number** 177662420636**Result** ✓ Passed**Minor** Central Front Windscreen damaged but not adversely affecting driver's view Chip Zone B (3.2 (a) (i))**MOT #1** 2019-03-04 15:40**MOT test number** 827977981031**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view Chip zone B (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
4 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 T6XXM
Plate since	2019-06-29
Current registration	 T6XXM
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-06-03
Last registration	2024-03-16
Complete history	See info



Registration #1	2016-06-03	6 mi
Registration #2	2019-03-04	40.318 mi
Registration #3	2020-03-18	48.486 mi
Registration #4	2021-03-16	51.067 mi
Registration #5	2021-03-25	51.103 mi
Registration #6	2022-03-20	51.277 mi
Registration #7	2023-03-20	51.277 mi
Registration #8	2023-03-20	51.277 mi
Registration #9	2023-03-20	51.277 mi
Registration #10	2024-03-16	51.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1990 mm
Length	4892 mm
Wheel base	3400 mm
Kerb weight	1855 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	3
Number of axles	2
Engine number	CAAA938089