



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Black
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-08
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-01
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	32
Total items failed	5

MOT #14 2024-02-14 12:48

MOT test number 522735703141

Result ✓ Passed

Next expiry date 2025-03-01

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))

MOT #13 2023-02-27 12:28

MOT test number 631777235920

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2022-02-21 12:31**MOT test number** 813425437928**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #11** 2021-02-25 14:38**MOT test number** 414871311769**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2020-02-25 12:35**MOT test number** 931317204789**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2019-02-26 12:30**MOT test number** 666710910008**Result** ✓ Passed**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement nearside and offside rear bush (5.3.4 (a) (i))**Advice** Nearside Front shock absorber upper bearing noisy**Advice** Rear Nearside and offside tyre tread inner edge abnormal wear

**MOT #8** 2018-02-19 12:10**MOT test number** 507935093362**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2018-02-19 12:10**MOT test number** 966645940827**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Pass with rectification** Offside Front Headlamp aim too low and too far to the right. (1.8)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #6** 2017-02-16 11:57**MOT test number** 696206040768**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #5** 2016-02-22 12:02**MOT test number** 105066286428**Result** ✓ Passed**Advice** Front wipers squeak**Advice** Both front tyres getting close wear bars

**MOT #4** 2015-02-24 11:14**MOT test number** 286195955022**Result** ✓ Passed**MOT #3** 2014-02-20 11:55**MOT test number** 475221754032**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-02-20 11:55**MOT test number** 926241154011**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #1** 2013-02-14 10:26**MOT test number** 937465743017**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 March 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	GK10XJZ
Plate since	2019-09-28
Current registration	GK10XJZ
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-01
Last registration	2024-02-14
Complete history	See info



Registration #1	2010-03-01	17 mi
Registration #2	2013-02-14	19.007 mi
Registration #3	2014-02-20	22.331 mi
Registration #4	2015-02-24	24.508 mi
Registration #5	2016-02-22	26.769 mi
Registration #6	2017-02-16	30.175 mi
Registration #7	2018-02-19	32.945 mi
Registration #8	2018-02-19	32.945 mi
Registration #9	2019-05-20	35.217 mi
Registration #10	2020-05-20	37.489 mi
Registration #11	2021-05-20	39.761 mi
Registration #12	2022-05-20	42.033 mi
Registration #13	2023-05-20	44.305 mi
Registration #14	2024-02-14	46.577 mi
Registration #15	2024-02-14	46.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1346 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	187111