



PEUGEOT

RA03GWL

report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S
Colour	Blue
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg






Internet history

Entry 1

Date	2021-09-30
Pictures	29
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT #25	2021-08-26 13:06
MOT test number	940029462031
Result	✓ Passed
Next expiry date	2022-08-25
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #24	2021-08-02 09:06
MOT test number	918965340586
Result	✗ Failed
Fail	Offside Rear Lower Suspension component mounting prescribed area excessively damaged significantly reducing structural strength (5.3.6 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))
Advice	Offside Rear Suspension spring mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))
Fail	Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))
Fail	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #23	2020-08-12 08:19
MOT test number	477877789750
Result	✓ Passed
MOT #22	2019-08-06 10:27
MOT test number	375903770573
Result	✓ Passed

**MOT #21** 2019-08-06 10:27**MOT test number** 764445105141**Result** ✗ Failed**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #20** 2018-08-01 13:02**MOT test number** 139166902801**Result** ✓ Passed**MOT #19** 2018-08-01 08:14**MOT test number** 597074837482**Result** ✗ Failed**Fail** Offside Rear Lower Shock absorbers insecurely attached (5.3.2 (a) (i))**Fail** Offside Front Lower Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**MOT #18** 2017-08-12 09:55**MOT test number** 915124442981**Result** ✓ Passed**MOT #17** 2016-08-03 16:00**MOT test number** 462961879107**Result** ✓ Passed**Advice** Nearside Rear Trailing arm has slight play in a pin/bush (2.4.G.2)**Advice** Oil leak engine oil leak**Advice** Offside Rear Trailing arm has slight play in a pin/bush (2.4.G.2)

**MOT #16** 2016-08-01 15:25**MOT test number** 626994783244**Result** ✗ Failed**Fail** Offside Front Lower Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Nearside Rear Trailing arm has slight play in a pin/bush (2.4.G.2)**Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Oil leak engine oil leak**Advice** Offside Rear Trailing arm has slight play in a pin/bush (2.4.G.2)**MOT #15** 2015-08-13 15:24**MOT test number** 675987744962**Result** ✓ Passed**MOT #14** 2014-08-05 15:47**MOT test number** 656497314249**Result** ✓ Passed**Notice** Rear suspension bush's perished

**MOT #13** 2014-08-05 10:07**MOT test number** 447597914297**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Notice** Rear suspension bush's perished**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**MOT #12** 2013-07-31 09:37**MOT test number** 169562413294**Result** ✓ Passed**MOT #11** 2013-07-31 09:37**MOT test number** 928762613208**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Front Registration plate lamp not working (1.1.C.1d)**MOT #10** 2012-07-30 16:26**MOT test number** 726272812261**Result** ✓ Passed**MOT #9** 2011-08-10 17:01**MOT test number** 845272921217**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #8** 2010-08-06 15:21**MOT test number** 641128610247**Result** ✓ Passed**MOT #7** 2010-08-06 10:06**MOT test number** 964708210203**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Centre Rear Exhaust has part of the system excessively deteriorated (7.1.1a)**MOT #6** 2009-08-25 14:44**MOT test number** 740257639227**Result** ✓ Passed**MOT #5** 2009-08-21 13:00**MOT test number** 521683339259**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2008-06-23 11:17**MOT test number** 211045578180**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly chafed (3.6.B.2c)**Notice** Rear brakes slightly binding**Advice** Offside Front Brake pipe slightly chafed (3.6.B.2c)



MOT #3	2007-06-25 11:34
MOT test number	400326777189
Result	✓ Passed

MOT #2	2007-06-25 11:34
MOT test number	714396177102
Result	✗ Failed
<div>Pass with rectification</div> Offside Rear Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)	

MOT #1	2006-06-27 11:32
MOT test number	134938976107
Result	✓ Passed
<div>Advice</div> Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
<div>Notice</div> Nearside rear tread worn to 2mm, limit =1.6mm.	
<div>Advice</div> Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>RA03GWL</b>
Plate since	2024-03-28
Current registration	<b>RA03GWL</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-06-30
Last registration	2021-08-26
Complete history	<a href="#">See info</a>



Registration #1	2003-06-30	15 mi
Registration #2	2006-06-27	33.195 mi
Registration #3	2007-06-25	43.280 mi
Registration #4	2008-06-23	52.761 mi
Registration #5	2009-08-21	61.496 mi
Registration #6	2009-08-25	61.496 mi
Registration #7	2010-08-06	65.429 mi
Registration #8	2010-08-06	65.429 mi
Registration #9	2011-08-10	67.553 mi
Registration #10	2012-07-30	72.086 mi
Registration #11	2013-07-31	77.206 mi
Registration #12	2014-08-05	79.387 mi
Registration #13	2014-08-05	79.389 mi
Registration #14	2015-08-05	81.511 mi
Registration #15	2016-08-05	83.633 mi
Registration #16	2017-08-05	85.755 mi
Registration #17	2018-08-05	87.877 mi
Registration #18	2019-08-05	89.999 mi
Registration #19	2020-08-05	92.121 mi
Registration #20	2021-08-05	94.243 mi
Registration #21	2022-08-05	96.365 mi
Registration #22	2023-08-05	98.487 mi
Registration #23	2024-08-05	100.609 mi
Registration #24	2025-08-05	102.731 mi
Registration #25	2026-08-05	104.853 mi



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1262 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	FX3V2063253