



report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE ACENTA
Colour	White
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 2

Date	2023-03-22
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-25
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-04-12
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	28
Total items failed	0

MOT #9	2024-04-12 11:13
MOT test number	930845753705
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8	2023-04-13 14:39
MOT test number	925842020350
Result	✓ Passed

MOT #7	2022-10-05 12:49
MOT test number	925688315878
Result	✓ Passed

MOT #6	2021-10-21 08:19
MOT test number	291286132626
Result	✓ Passed



<b>MOT #5</b>	2021-01-22 13:31
<b>MOT test number</b>	706724675792
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge 2.7mm (5.2.3 (e))

<b>MOT #4</b>	2019-06-24 15:41
<b>MOT test number</b>	933672564470
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #3</b>	2019-06-24 11:25
<b>MOT test number</b>	373226429435
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>DANGEROUS</b>	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #2** 2018-06-28 08:55**MOT test number** 823872315861**Result** ✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #1** 2018-06-27 13:43**MOT test number** 407890095583**Result** ✗ Failed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Rear Windscreen wiper blade defective (3.4 (b) (i))
- MAJOR** Offside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure Sidewall been rubbing,has started to bulge. (5.2.3 (d) (i))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
12 April 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	368
<b>MOT expiry date</b>	12 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-07-24
Last registration	2024-04-12
Complete history	<a href="#">See info</a>



Registration #1	2015-07-24	20 mi
Registration #2	2018-06-27	36.508 mi
Registration #3	2018-06-28	36.508 mi
Registration #4	2019-06-24	48.031 mi
Registration #5	2019-06-24	48.031 mi
Registration #6	2021-01-22	61.616 mi
Registration #7	2022-05-22	75.277 mi
Registration #8	2022-05-22	75.277 mi
Registration #9	2022-05-22	75.277 mi
Registration #10	2022-05-22	75.277 mi
Registration #11	2022-05-22	75.277 mi
Registration #12	2024-04-12	89.000 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1040 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	094515R