





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	IX35 GDI S
Colour	White
Year of manufacture	2014
Top speed	111 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	133 BHP
Max. torque	165 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/12



### Internet history

#### Entry 1

Date 2021-10-22

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



**EX14SXT** 

report date: 2024-03-28

## MOT history

MOT expiry date	2024-05-02
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	9
Total items failed	6

MOT #10	2023-05-03 15:28
MOT test number	642861194757
Result	<b>✓</b> Passed
Next expiry date	2024-05-02

MOT #9	2022-03-05 08:31
MOT test number	247172907560
Result	✓ Passed

MOT #8	<b>B</b> 2022-03-02 14:30
MOT te	st number 305656418785
Result	<b>★</b> Failed
Fail (a))	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2

MOT #7	2021-04-29 11:19
MOT test number	579832686613
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #6 2021-04-23 15:48

**MOT test number** 504101270336

Result X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #5** 2019-10-07 16:29

MOT test number 244080729824

**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2019-10-07 13:14

MOT test number 133042646188

**Result** X Failed

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2018-09-26 07:45

MOT test number 238539230069

**Result** ✓ Passed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Minor Nearside Front Tyre pressure monitoring system warning lamp indicates a fault non tpms valve

fitted (5.2.3 (h) (i))

CarCheck.co.uk page 4/12



MOT #2 2018-09-24 07:08

**MOT test number** 124629375270

Result

× Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Nearside Front Tyre pressure monitoring system warning lamp indicates a fault non tpms valve fitted (5.2.3 (h) (i))

MOT #1 2017-04-13 11:42

**MOT test number** 370077784483

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	2 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when mistery		
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		ΑI
********		
***************************************		
***************************************		
	More info >	
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		9
Current registration	NK NE	
Plate since		
Current registration	NK NEW TOTAL	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-05
Last registration	2023-05-03
Complete history	See info



Registration #1	2014-03-05	25 mi
Registration #2	2017-04-13	31.939 mi
Registration #3	2018-09-24	48.205 mi
Registration #4	2018-09-26	48.205 mi
Registration #5	2019-10-07	61.809 mi
Registration #6	2019-10-07	61.818 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		10.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1820 mm
Height	1655 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

# Additional information

Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

**Engine number** G4FDEZ867300