



report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	310 Nm at 1.300 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history


Entry 2

Date	2022-04-15
Pictures	0
Listing price	View report

source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-22
Pictures	4
Listing price	View report




AA Dealer Promise

AA

You're in safe hands
This dealer has signed our Dealer Promise.


AAACARS.COM



NEW STOCK!!!

JUST ARRIVED

PICTURES COMING SOON




AA

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com



Call or WhatsApp
01443552166
[sidautos.co.uk](#)

source: [cargurus.co.uk](#)

**MOT history**

MOT expiry date	2024-07-20
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	16
Total items failed	15

MOT #13 2023-07-19 14:51**MOT test number** 506483844866**Result** Passed**Next expiry date** 2024-07-20**Advice** Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12** 2022-07-21 14:59**MOT test number** 383427784958**Result** Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #11** 2021-11-24 19:50**MOT test number** 540125498015**Result** Passed

**MOT #10** 2021-11-24 19:50**MOT test number** 829915946971**Result** ✗ Failed

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Front Position lamp not working both (4.2.1 (a) (ii))

MOT #9 2021-03-01 16:27**MOT test number** 623808407020**Result** ✓ Passed

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Front and rear brake discs lipped/worn

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #8 2019-06-11 11:20**MOT test number** 701290299678**Result** ✓ Passed

Advice Exhaust system corroded.

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Play in steering rack inner joint(s)

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #7 2018-06-26 11:27**MOT test number** 653109345736**Result** ✓ Passed**MOT #6** 2017-06-14 08:09**MOT test number** 490214502366**Result** ✓ Passed

**MOT #5**

2017-06-13 08:00

MOT test number

188772853449

Result**✗ Failed**

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Central Stop lamp not working (1.2.1b)

Fail Registration plate lamp not working (1.1.C.1d)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Stop lamp not working (1.2.1b)

MOT #4

2016-06-20 10:11

MOT test number

948886976362

Result**✓ Passed**

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

2016-06-13 12:58

MOT test number

151301694222

Result**✗ Failed**

Fail Centre Stop lamp not working (1.2.1b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

Fail Offside Stop lamp not working (1.2.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

Fail Registration plate lamp not working (1.1.C.1d)



MOT #2	2015-06-18 10:20
MOT test number	277449065169
Result	✓ Passed

MOT #1	2015-06-18 10:20
MOT test number	696699265136
Result	✗ Failed
Pass with rectification	Registration plate lamp not working (1.1.C.1d)
Pass with rectification	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Pass with rectification	Centre Stop lamp not working (1.2.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
20 July 2024

Tax status		Valid until 1 July
Days left		62
MOT expiry date		20 July 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-28
Last registration	2023-07-19
Complete history	See info



Registration #1	2012-06-28	15 mi
Registration #2	2015-06-18	83.116 mi
Registration #3	2016-06-13	103.833 mi
Registration #4	2016-06-20	104.140 mi
Registration #5	2017-06-13	118.698 mi
Registration #6	2017-06-14	118.700 mi
Registration #7	2018-06-26	123.579 mi
Registration #8	2019-06-11	133.559 mi
Registration #9	2020-06-20	143.539 mi
Registration #10	2021-06-20	153.519 mi
Registration #11	2022-06-20	163.499 mi
Registration #12	2023-06-20	173.479 mi
Registration #13	2024-06-20	183.459 mi
Registration #14	2025-06-20	193.439 mi
Registration #15	2026-06-20	203.419 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	BM22990