



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Red
Year of manufacture	2007
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-06
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-29
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	29
Total items failed	5

MOT #16	2023-10-30 15:41
MOT test number	983100706433
Result	✓ Passed
Next expiry date	2024-10-29
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15	2023-10-30 10:36
MOT test number	454258790473
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14**

2022-10-28 11:15

**MOT test number**

254811969007

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13**

2022-10-26 15:39

**MOT test number**

895714155225

**Result**

✗ Failed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**Fail** Offside Front Lower Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))**MOT #12**

2021-10-21 09:32

**MOT test number**

113190297384

**Result**

✓ Passed

**MOT #11**

2021-03-19 14:27

**MOT test number**

250664934809

**Result**

✓ Passed

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10**

2019-07-23 09:08

**MOT test number**

557134712597

**Result**

✓ Passed

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #9**

2018-07-25 13:18

**MOT test number**

301567828501

**Result**

✓ Passed

**MOT #8**

2017-04-07 09:26

**MOT test number**

688637995263

**Result**

✓ Passed

**Advice**

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**Advice**

Front registration plate deteriorated but not likely to be misread (6.3.1d)

**Advice**

Rear Tyre worn close to the legal limit both (4.1.E.1)

**MOT #7**

2016-04-28 08:52

**MOT test number**

888214849068

**Result**

✓ Passed

**Advice**

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice**

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Front registration plate delaminated but not likely to be misread (6.3.1d)

**Advice**

No smoke reading

**Advice**

Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2015-04-01 14:04**MOT test number** 858291295081**Result** ✓ Passed**MOT #5** 2014-03-14 13:22**MOT test number** 848613974060**Result** ✓ Passed**Notice** Smoke test to clean for reading**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2013-03-11 16:08**MOT test number** 737390173059**Result** ✓ Passed**MOT #3** 2012-01-16 09:50**MOT test number** 779666112010**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-01-28 10:11**MOT test number** 658508121086**Result** ✓ Passed**MOT #1** 2010-02-02 15:36**MOT test number** 393943630097**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
29 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	29 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-01-26
Last registration	2023-10-30
Complete history	<a href="#">See info</a>



Registration #1	2007-01-26	10 mi
Registration #2	2010-02-02	3.599 mi
Registration #3	2011-01-28	4.593 mi
Registration #4	2012-01-16	6.446 mi
Registration #5	2013-03-11	8.658 mi
Registration #6	2014-03-14	11.000 mi
Registration #7	2015-04-01	13.495 mi
Registration #8	2016-04-28	14.492 mi
Registration #9	2017-04-07	14.520 mi
Registration #10	2018-05-20	15.277 mi
Registration #11	2019-05-20	16.277 mi
Registration #12	2020-05-20	17.277 mi
Registration #13	2021-05-20	18.277 mi
Registration #14	2022-05-20	19.277 mi
Registration #15	2023-05-20	20.277 mi
Registration #16	2024-05-20	21.277 mi
Registration #17	2025-05-20	22.277 mi
Registration #18	2026-05-20	23.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg
Max. allowed weight	2550 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040368471