





report date: 2024-03-29

General information

Make	MASERATI
Model	LEVANTE D V6 AUTO D V6
Colour	Grey
Year of manufacture	2017
Top speed	143 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	271 BHP
Max. torque	600 Nm at 2.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	42.8 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2021-09-23

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-09-05

Pictures 61

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1


Date 2021-08-28

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-07-27
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #6	2023-07-15 13:16
MOT test number	236982238647
Result	✓ Passed
Next expiry date	2024-07-27

MOT #5	2022-07-20 13:31
MOT test number	771700333104
Result	✓ Passed

MOT #4		2021-07-22 10:56
MOT tes	t number	401136103474
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/11



MOT #3 2020-07-28 15:37

MOT test number 844169055453

Result \rightarrow Passed

Advice Nearside Front Tyre slightly damaged damage on outer face rim protector (5.2.3 (d) (ii))

Advice Rear Road wheel slightly distorted both (5.2.2 (c) (i))

MOT #2 2020-07-28 10:17

MOT test number 407003273408

Result X Failed

DANGEROUS Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure inner face (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm and worn on the inner edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged damage on outer face rim protector (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge on the legal limit 1.6mm (5.2.3 (e))

MOT #1 2020-07-06 05:42

MOT test number 392341105660

Result \(\sqrt{Passed} \)

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MASERATI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	history
O WILCI	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

o milet matery			
		have this MASERATI? How many o I see all owner registrations. Dowr	

Plate changes			More info >
See in this check if this M	ASERATI had different num	ber plates.	
Number of plates			,
Current registration			NK UK
Plate since			
Current registration			OK OK
Plate since			
			More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-07-14
Last registration	2023-07-15
Complete history	See info



Registration #1	2017-07-14	19 mi
Registration #2	2020-07-28	21.549 mi
Registration #3	2020-07-28	21.549 mi
Registration #4	2021-07-22	28.599 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.177 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Dimensions & weight

Width	1968 mm
Height	1679 mm
Length	5003 mm
Wheel base	3004 mm
Kerb weight	2280 kg
Max. allowed weight	2900 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	008093

CarCheck.co.uk page 11/11