





report date: 2024-03-28

General information

| Make | VOLKSWAGEN |
|---------------------|----------------|
| Model | POLO SE TDI |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 106 mph |
| 0 - 60 mph | 13.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 75 BHP |
|-------------------------|---------------------|
| Max. torque | 195 Nm at 1.500 rpm |
| Engine capacity | 1.598 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 55.4 mpg |
| Consumption extra urban | 78.5 mpg |
| Consumption combined | 67.3 mpg |
| CO2 emission | 112 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-07-30 |
|--------------------|------------|
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 18 |
| Total items failed | 0 |

| MOT #13 | 2023-07-06 06:47 |
|----------------------------|------------------|
| MOT test number | 685109109560 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-30 |
| Advice Coolant leak | |
| Advice Exhaust deterioated | |

| MOT #12 | | 2023-07-04 13:01 |
|--|---------------------|------------------|
| MOT test | number | 689064689970 |
| Result | | X Failed |
| Advice | Exhaust deterioated | |
| MAJOR Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced sill area (7.1.1 (a) (i)) | | |
| Advice | Coolant leak | |

| MOT #11 | 2022-07-08 10:15 |
|--|------------------|
| MOT test number | 484234165337 |
| Result | ✓ Passed |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a |) (i)) |

CarCheck.co.uk page 2/11



report date: 2024-03-28

Passed

MOT #10 2021-07-09 12:10

MOT test number 236898743613

MOT #9 2020-07-31 11:05

MOT test number 962055433078

Result

Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2020-07-30 15:26

MOT test number 109366764983

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2018-07-26 11:48

MOT test number 366903513475

Result

Passed

MOT #6 2017-08-18 10:19

MOT test number 486326960792

Advice Nearside Play in steering rack inner joint(s)

Result

MOT #5 2016-08-22 14:38

MOT test number 181737639959

Result

Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

506247035196

Advice

Rear exhaust box slightly corroded

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

676633033322

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #1
 2012-12-11 12:57

 MOT test number
 608876242357

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 64 |
| MOT expiry date | 30 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here. | |
| *************************************** | |
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | BB-0-0 |
| Current registration | OK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2010-01-30 |
| Last registration | 2023-07-06 |
| Complete history | See info |



| Registration #1 | 2010-01-30 | 24 mi |
|------------------|------------|-----------|
| Registration #2 | 2012-12-11 | 30.422 mi |
| Registration #3 | 2013-11-29 | 38.602 mi |
| Registration #4 | 2014-12-01 | 47.403 mi |
| Registration #5 | 2015-12-02 | 54.499 mi |
| Registration #6 | 2016-08-22 | 59.029 mi |
| Registration #7 | 2017-08-18 | 64.398 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| | | |

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| 50225 | Air conditionir |
|-------|-----------------|
| 50295 | |
| 60482 | |
| 60501 | |
| 60566 | |
| 0567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 86% |
| Pedestrian | 41% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1682 mm |
|---------------------|---------|
| Height | 1485 mm |
| Length | 3970 mm |
| Wheel base | 2470 mm |
| Kerb weight | 1157 kg |
| Max. allowed weight | 1650 kg |

Additional information

| Fuel tank capacity | 45 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| CarChack co.uk | nago 11/11 |

CarCheck.co.uk page 11/11

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | CAY 727845 |