





report date: 2024-03-29

#### General information

Make	FIAT
Model	500 C POP
Colour	Grey
Year of manufacture	2011
Top speed	107 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date 2022-01-27

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-27
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	23
Total items failed	1

MOT #11	2024-01-17 13:11
MOT test number	339376705597
Result	<b>✓</b> Passed
Next expiry date	2025-01-27

MOT #10		2023-01-19 09:11
<b>MOT</b> test	number	368030366283
Result		✓ Passed
Advice	Exhaust has a minor leak of exhaust gases front flexi (6.1.2 (a))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		sive movement (5.3.4

MOT #9		2022-01-28 11:44
MOT test	number	334811612652
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



MOT test number

388625809047

Result

Advice Macpherson strut pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))

Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

Advice Exhaust has a minor leak of exhaust gases middle exhaust (6.1.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7	2020-01-20 15:31
MOT test number	423044472419
Result	<b>✓</b> Passed
MOT #6	2019-02-11 16:32
MOT test number	330881533484
Result	<b>✓</b> Passed
Advice Nearside Front Nail in tyre	

CarCheck.co.uk page 4/13



MOT #5 2018-01-27 12:30

MOT test number 978325743824

**Result** ✓ Passed

**Advice** Engine covers fitted

**Advice** Rear Direction indicators slightly discoloured both (1.4.A.2f)

**Advice** Spare tyre low in pressure

**Advice** Exhaust system deteriorating

**Advice** Vehicles internal headlight adjuster altered to recheck lights

Advice Under-trays fitted

**Advice** Rear wiper blade split

**Advice** Nearside Front Suspension arm has slight play in a ball joint bottom ball joint (2.4.G.2)

**Advice** Both front tyres worn smooth on inner edge

MOT #4 2017-02-23 14:06

**MOT test number** 211560530274

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)

**Advice** Both front tyres wearing on shoulders

MOT #3 2017-02-21 17:03

**MOT test number** 179540541459

Result X Failed

**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)

**Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)

**Advice** Both front tyres wearing on shoulders

CarCheck.co.uk page 5/13



MOT #2

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

 MOT #1
 2014-08-06 16:51

 MOT test number
 717978014228

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	27 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and provious owner(s) have this FIAT2 How many owners di	id this FIAT have?
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
HARMANN	
***************************************	
*********	
***************************************	
************	
	More info >
	Piore inio
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-09-01
Last registration	2024-01-17
Complete history	See info



Registration #1	2011-09-01	13 mi
Registration #2	2014-08-06	6.657 mi
Registration #3	2015-08-15	8.895 mi
Registration #4	2017-02-21	21.526 mi
Registration #5	2017-02-23	21.531 mi
Registration #6	2018-01-27	25.676 mi
Registration #7		91.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/1.

Number of axles2Engine number0012511