



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Black
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-26
Pictures	21
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-05-22
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	3

MOT #12	2023-05-23 12:30
MOT test number	682664149813
Result	✓ Passed
Next expiry date	2024-05-22
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #11	2022-05-21 16:24
MOT test number	434709235920
Result	✓ Passed

MOT #10	2022-05-21 15:35
MOT test number	379643159443
Result	✗ Failed
MAJOR	Electronic stability control warning lamp indicates a fault (7.12 (e))
DANGEROUS	Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
DANGEROUS	Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #9** 2020-11-24 11:28**MOT test number** 256146697084**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #8** 2019-11-25 11:07**MOT test number** 775306756051**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2018-11-23 12:21**MOT test number** 192695063746**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge n/s and o/s (5.2.3 (e))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt o/s and n/s**MOT #6** 2017-12-07 12:57**MOT test number** 872986005014**Result** ✓ Passed**MOT #5** 2017-12-07 12:57**MOT test number** 739842794645**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Pass with rectification** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

**MOT #4** 2016-12-02 15:21**MOT test number** 203755151786**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2015-11-30 11:33**MOT test number** 383357887523**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-12-04 09:22**MOT test number** 685628234334**Result** ✓ Passed**MOT #1** 2014-12-04 09:22**MOT test number** 766918834352**Result** ✗ Failed**Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
22 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	22 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>VE61BHN</b>
Plate since	2024-03-29
Current registration	 <b>VE61BHN</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-12-06
Last registration	2023-05-23
Complete history	<a href="#">See info</a>



Registration #1	2011-12-06	28 mi
Registration #2	2014-12-04	68.797 mi
Registration #3	2015-11-30	76.431 mi
Registration #4	2016-12-02	85.406 mi
Registration #5	2017-12-07	94.234 mi
Registration #6	2017-12-07	94.234 mi
Registration #7	2018-11-23	104.396 mi
Registration #8	2019-05-23	104.396 mi
Registration #9	2019-05-23	104.396 mi
Registration #10	2019-05-23	104.396 mi
Registration #11	2019-05-23	104.396 mi
Registration #12	2019-05-23	104.396 mi
Registration #13	2019-05-23	104.396 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

CAY 586764