



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Grey
Year of manufacture	2010
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 2

Date	2023-02-19
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2022-02-12
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-12-17
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	26
Total items failed	10

MOT #15	2023-12-18 12:31
MOT test number	162523107245
Result	✓ Passed
Next expiry date	2024-12-17

MOT #14	2023-10-04 15:23
MOT test number	785358690720
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Front Brake disc worn, but not excessively both (1.1.14 (a) (i))

MOT #13	2022-10-04 07:54
MOT test number	708357586876
Result	✓ Passed
Minor	Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12** 2022-10-04 07:54**MOT test number** 292603731933**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #11** 2021-10-11 12:44**MOT test number** 637477210254**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2021-10-04 07:44**MOT test number** 868229309092**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #9** 2019-07-14 10:54**MOT test number** 876414137636**Result** ✓ Passed**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Minor** Front Position lamp incorrect colour offside and nearside front amber side markers lamps working as position lamps (4.2.3 (a) (i))

**MOT #8** 2018-06-08 10:45**MOT test number** 436158061886**Result** ✓ Passed**Advice** Under guards obscuring some components for test**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Engine guard obscuring some components for test**MOT #7** 2017-06-27 08:53**MOT test number** 574790526573**Result** ✓ Passed**Advice** Under-trays fitted obscuring some underside components**Advice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2017-06-26 09:52**MOT test number** 103059027904**Result** ✗ Failed**Advice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Engine covers fitted obscuring some components in the engine bay**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #5** 2016-06-08 09:47**MOT test number** 960902179968**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both fronts (3.5.1i)**Advice** Brake pad(s) wearing thin both fronts (3.5.1g)

**MOT #4** 2016-06-08 09:47**MOT test number** 705513569603**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Brake pad(s) wearing thin both fronts (3.5.1g)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Brake disc worn, pitted or scored, but not seriously weakened both fronts (3.5.1i)**MOT #3** 2015-10-05 11:11**MOT test number** 469097434981**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2014-10-14 08:54**MOT test number** 608887984231**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #1** 2013-10-15 09:38**MOT test number** 568848183218**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
17 December 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	17 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-10-29
Last registration	2023-12-18
Complete history	<a href="#">See info</a>



Registration #1	2010-10-29	11 mi
Registration #2	2013-10-15	39.974 mi
Registration #3	2014-10-14	55.734 mi
Registration #4	2015-10-05	74.251 mi
Registration #5	2016-06-08	90.081 mi
Registration #6	2016-06-08	90.081 mi
Registration #7	2017-06-26	110.278 mi
Registration #8	2017-06-27	110.278 mi
Registration #9	2018-06-08	125.551 mi
Registration #10	2019-06-08	140.824 mi
Registration #11	2020-06-08	156.097 mi
Registration #12	2021-06-08	171.370 mi
Registration #13	2022-06-08	186.643 mi
Registration #14	2023-06-08	201.916 mi
Registration #15	2024-06-08	217.189 mi
Registration #16	2025-06-08	232.462 mi
Registration #17	2026-06-08	247.735 mi
Registration #18	2027-06-08	263.008 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	701649