





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|--------------------|
| Model | TRANSIT 290 LR P/V |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 10 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 114 kW / 155 HP / 98 BHP |
|-------------------------|--------------------------|
| Max. torque | 330 Nm at 1.600 rpm |
| Engine capacity | 2.198 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 33.6 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 186 g/km |
| CO2 label | J |



CarCheck.co.uk page 1/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-02-06 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 15 |
| Total items failed | 4 |

| MOT #8 | 2024-02-05 11:23 |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| MOT test number | 808971128703 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-06 |
| Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush in arm (5.3.4 (a) (i)) Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement | |
| Rear bush in arm (5.3.4 (a) (i)) | |

| MOT #7 | 2023-02-07 15:20 |
|-----------------------------------------------|------------------|
| MOT test number | 379328976916 |
| Result | ✓ Passed |
| Advice All brake discs have surface corrosion | |

| MOT #6 | 2023-02-06 12:25 |
|-------------------------------------------------------------|------------------|
| MOT test number | 304558962495 |
| Result | × Failed |
| Advice All brake discs have surface corrosion | |
| Fail Rear Brake pipe excessively corroded axle (1.1.11 (c)) | |
| Fail Nearside Side repeater not working (4.4.1 (a) (ii)) | |
| Fail Windscreen washer not working (3.5 (a)) | |

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT #5 2021-08-26 08:14

MOT test number 365474336418

Result \rightarrow Passed

Advice Brake pipe corroded, covered in grease or other material across rear beam (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2020-08-27 12:19

MOT test number 510067459384

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))

MOT #3 2019-08-22 10:19

MOT test number 127786921605

Result \(\sqrt{Passed} \)

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Tyre worn close to legal limit/worn on edge front & rear (5.2.3 (e))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Wheel caps fitted

MOT #2 2018-05-23 08:50

MOT test number 728491269389

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2018-05-23 08:50

MOT test number 116831488750

Result X Failed

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Pass with rectification

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 34 |
| MOT expiry date | 6 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

| \sim | | |
|--------|---------|---|
| Owner | hictory | 7 |
| OWITCE | 1113601 | 1 |

| For how long did the current and previous owner(s) have this FORD? How many owners defined the current and see all owner registrations. Download the full report in the premium report and see all owner registrations. | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| | |
| | |
| | |
| | |
| manage of the same | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | |
| Current registration | IK SIN |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



BK15ZSR report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2015-05-27 |
| Last registration | 2024-02-05 |
| Complete history | See info |



| Registration #1 | 2015-05-27 | 24 mi |
|-----------------|------------|-----------|
| Registration #2 | 2018-05-23 | 48.085 mi |
| Registration #3 | 2018-05-23 | 48.085 mi |
| Registration #4 | 2019-08-22 | 67.029 mi |
| Registration #5 | 2020-08-27 | 81.391 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 10.777 es |

More info >

CarCheck.co.uk page 10/11



BK15ZSR report date: 2024-03-28

Car features

| 50225 | Air conditionir |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 60566 | |
| 0567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 90% |
| Pedestrian | 48% |
| Safety systems | 71% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| Width | 2272 mm |
|---------------------|---------|
| Height | 1922 mm |
| Length | 4972 mm |
| Wheel base | 3300 mm |
| Kerb weight | 1817 kg |
| Max. allowed weight | 2900 kg |

Additional information

| Fuel tank capacity | 80 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of axles CarCheck.co.uk | 2 page 11/ |