



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Blue
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	98 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	3
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-04-15
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	25
Total items failed	12

MOT #13 2024-04-11 08:58

MOT test number 248663187520

Result ✓ Passed

Next expiry date 2025-04-15

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #12 2024-04-10 10:54

MOT test number 598848551483

Result ✗ Failed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Reversing lamp inoperative (4.6.1 (a))

**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Exhaust system insecure 2 out of 3 mountings broken (6.1.2 (a))



<b>MOT #11</b>	2023-03-30 12:17
<b>MOT test number</b>	252227864372
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Service brake fluctuating, but not excessively (1.2.1 (e))

<b>MOT #10</b>	2023-03-30 08:15
<b>MOT test number</b>	560051365638
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Front Service brake fluctuating, but not excessively (1.2.1 (e))

<b>MOT #9</b>	2022-04-13 12:01
<b>MOT test number</b>	959792279414
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge N/S & O/S (5.2.3 (e))



## MOT #8

2022-04-13 12:01

MOT test number

847046745676

## Result

✗ Failed

**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Advice** Front Tyre worn close to legal limit/worn on edge N/S & O/S (5.2.3 (e))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Front Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #7

2021-04-16 13:41

MOT test number

702362381976

## Result

✓ Passed

## MOT #6

2021-04-15 15:37

MOT test number

408395554861

## Result

✗ Failed

**Fail** Windscreen washer not working (3.5 (a))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #5** 2020-11-11 16:55**MOT test number** 292185444117**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-05-16 11:27**MOT test number** 366092209920**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2018-05-17 15:12**MOT test number** 701551280867**Result** ✓ Passed**MOT #2** 2017-05-17 10:08**MOT test number** 650821880279**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2016-03-17 14:17**MOT test number** 677261666634**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
15 April 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	15 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-31
Last registration	2024-04-11
Complete history	<a href="#">See info</a>



Registration #1	2013-03-31	22 mi
Registration #2	2016-03-17	5.070 mi
Registration #3	2017-05-17	16.389 mi
Registration #4	2018-05-17	21.706 mi
Registration #5	2019-05-16	25.925 mi
Registration #6	2020-11-11	31.931 mi
Registration #7	2020-05-20	31.377 mi
Registration #8	2021-04-15	32.338 mi
Registration #9	2020-05-20	31.377 mi
Registration #10	2020-05-20	31.377 mi
Registration #11	2020-05-20	31.377 mi
Registration #12	2020-05-20	31.377 mi
Registration #13	2020-05-20	31.377 mi
Registration #14	2020-05-20	31.377 mi
Registration #15	2020-05-20	31.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3067047