



EKI20HT

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 350 H/R P/V
Colour	Black
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	153 BHP
Max. torque	385 Nm at 1.600 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	38.2 mpg
Consumption combined	34.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-10
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-10-30
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	45
Total items failed	16

MOT #17	2023-10-31 12:50
MOT test number	636906699370
Result	✓ Passed
Next expiry date	2024-10-30
Advice	Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2023-10-30 14:34

MOT test number

300935512866

Result**✗ Failed****DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Rear Lower Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Nearside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #15**

2022-10-18 11:47

MOT test number

792642390844

Result**✓ Passed****MOT #14**

2021-06-09 05:41

MOT test number

502219554975

Result**✓ Passed****Advice** Nearside n/s mirror cover missing (replaced)**Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both rear antiroll bushes slightly worn (5.3.4 (a) (i))

**MOT #13**

2021-06-09 05:41

MOT test number

479577441255

Result**✗ Failed**

Advice Anti-roll bar pin or bush worn but not resulting in excessive movement both rear antiroll bushes slightly worn (5.3.4 (a) (i))

Pass with rectification Nearside Front Upper Position lamp not working (4.2.1 (a) (ii))

Advice Nearside n/s mirror cover missing (replaced)

MOT #12

2020-06-01 07:45

MOT test number

580989492747

Result**✓ Passed**

Minor Nearside Rear Inner Tyre obviously under inflated (5.2.3 (I))

MOT #11

2019-05-20 10:56

MOT test number

716811595889

Result**✓ Passed****MOT #10**

2019-05-17 09:42

MOT test number

871437751593

Result**✗ Failed**

MAJOR Nearside Front Position lamp not working (4.2.1 (a))

MAJOR Offside Front Upper Outline marker lamp not working (4.2.1 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Nearside Front Upper Outline marker lamp not working (4.2.1 (a))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #9	2018-06-12 15:28
MOT test number	156199477166
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2018-05-15 12:16
MOT test number	879999943120
Result	✗ Failed
Fail	Nearside Obligatory mirror seriously obscured affecting the rear view (8.1.2a)
Advice	Near side front upper marker light n/w
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
Fail	Nearside Rear position lamp(s) not working (1.1.A.3b)
Advice	Offside rear lamp support bracket bent.
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7	2017-05-25 14:15
MOT test number	930080639291
Result	✓ Passed
Advice	Nearside Obligatory mirror obscured but not seriously affecting the rear view (8.1.2a)
Advice	Near side front upper marker light n/w
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Offside rear lamp mounting bracket damage.

**MOT #6**

2017-05-25 12:02

MOT test number

591403874902

Result**✗ Failed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear fog lamp not working (1.3.2b)**Advice** Offside rear lamp mounting bracket damage.**Advice** Nearside Obligatory mirror obscured but not seriously affecting the rear view (8.1.2a)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Brake pedal anti-slip provision incomplete (3.3.A.1b)**Advice** Near side front upper marker light n/w**MOT #5**

2016-05-27 07:48

MOT test number

626434032534

Result**✓ Passed****Advice** Offside Rear Tyre worn close to the legal limit inner (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4**

2016-05-26 10:07

MOT test number

310016355477

Result**✗ Failed****Fail** Front registration plate faded (6.3.1d)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit inner (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #3** 2015-05-20 12:04**MOT test number** 527130245157**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-05-07 13:37**MOT test number** 869657625181**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2015-05-07 12:29**MOT test number** 218157225148**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Offside Front Headlamp aim too low (1.8)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Upper Front position lamp(s) not working (1.1.A.3b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
30 October 2024

Tax status		Valid until 1 October
Days left		156
MOT expiry date		30 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EK12OHT
Plate since	2019-03-28
Current registration	EK12OHT
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-04-27
Last registration	2023-10-31
Complete history	See info



Registration #1	2012-04-27	13 mi
Registration #2	2015-05-07	49.189 mi
Registration #3	2015-05-07	49.192 mi
Registration #4	2015-05-20	49.218 mi
Registration #5	2016-05-26	50.986 mi
Registration #6	2016-05-27	50.986 mi
Registration #7	2017-05-25	52.368 mi
Registration #8	2017-05-25	52.368 mi
Registration #9	2018-05-15	53.652 mi
Registration #10	2018-06-12	53.694 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi
Registration #18	2019-05-20	55.277 mi
Registration #19	2019-05-20	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	CB51893