





report date: 2024-03-28

### General information

| Make                | TOYOTA                |
|---------------------|-----------------------|
| Model               | AURIS VALVEMATIC ICON |
| Colour              | Blue                  |
| Year of manufacture | 2014                  |
| Top speed           | 124 mph               |
| 0 - 60 mph          | 10.0 seconds          |
| Gearbox             | 6 speed Manual        |

### Engine & fuel consumption

| Power                   | 132 BHP             |
|-------------------------|---------------------|
| Max. torque             | 160 Nm at 4.400 rpm |
| Engine capacity         | 1.598 сс            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 35.8 mpg            |
| Consumption extra urban | 58.9 mpg            |
| Consumption combined    | 47.9 mpg            |
| CO2 emission            | 138 g/km            |
| CO2 label               | Е                   |



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date    | 2024-09-18 |
|--------------------|------------|
| MOT pass rate      | 88 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 1          |
| Total advice items | 8          |
| Total items failed | 0          |

| MOT #8           | 2023-09-19 14:45 |
|------------------|------------------|
| MOT test number  | 188319015198     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-09-18       |

| MOT #7          | 2023-01-26 09:22 |
|-----------------|------------------|
| MOT test number | 797192711941     |
| Result          | ✓ Passed         |

| 2022-01-18 14:42 |
|------------------|
| 385477789549     |
| <b>✓</b> Passed  |
|                  |

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

| MOT #5          | 2021-01-19 09:59 |
|-----------------|------------------|
| MOT test number | 318297113667     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 3/11



report date: 2024-03-28

| MOT #4         |   | 2020-07-08 10:25     |
|----------------|---|----------------------|
| MOT test       | number  | 568948140913         |
| Result         |   | 🗙 Failed             |
| Advice         | Nearside Front Tyre has a cut but not deep enough to reach the ply or cords ( | 5.2.3 (d) (i))       |
| Advice         | Front front foglights inoperative bulbs missing                               |                      |
| MAJOR<br>(ii)) | Front Windscreen wiper does not clear the windscreen effectively both front w | ripers worn (3.4 (b) |

| MOT #3   |   | 2019-07-29 08:08 |
|----------|---|------------------|
| MOT test | number  | 447333761400     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge 3.70mm (5.2.3 (e))      |                  |
| Advice   | Nearside Rear Nail in tyre  |                  |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge 3.70mm (5.2.3 (e))     |                  |
| Advice   | Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 | 1 (a) (ii))      |

| MOT #2          | 2018-08-08 08:08 |
|-----------------|------------------|
| MOT test number | 525888200691     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2017-08-11 14:03 |
| MOT test number | 733516738173     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check





Expires: 18 September 2024

| Tax status       | Valid until 1 September |
|------------------|-------------------------|
| Days left        | 124                     |
| MOT expiry date  | 18 September 2024       |
| Full MOT history | See MOT history         |

#### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| venicie ciass                           | 40         |
| Band                                    | Е          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| •  |           |     |
|--|-----------|-----|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r  |           | )TA |
|  |           |     |
|  |           |     |
|  |           |     |
|  |           |     |
| THE STATE OF THE S |           |     |
|  |           |     |
| ***************************************  |           |     |
|  | More info | >   |
| Plate changes  See in this check if this TOYOTA had different number plates.   |           |     |
| Number of plates   |           | ,   |
| Current registration   | UK UK     |     |
| Plate since  |           |     |
| Current registration   | UK UK     |     |
| Plate since  |           |     |
|  | More info | >   |
|  |           |     |

CarCheck.co.uk page 8/11



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 10         |
| First mileage registration | 2014-09-01 |
| Last registration          | 2023-09-19 |
| Complete history           | See info   |



| Registration #1                 | 2014-09-01 | 19 mi                            |
|---------------------------------|------------|----------------------------------|
| Registration #2                 | 2017-08-11 | 20.427 mi                        |
| Registration #3                 | 2018-08-08 | 23.516 mi                        |
| Registration #4                 | 2019-07-29 | 26.248 mi                        |
| Registration #5                 | 2020-07-08 | 43.625 mi                        |
|                                 |            |                                  |
| Registration #6                 |            | 11.777 es                        |
| Registration #6 Registration #7 |            | 11.00 m                          |
| •                               |            | 11.77 m<br>11.77 m               |
| Registration #7                 |            | 11.77 es<br>11.77 es<br>11.77 es |

More info >

CarCheck.co.uk page 10/11



## Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 |                 |
| 50482 |                 |
| 50501 |                 |
| 50566 |                 |
| 50567 |                 |
| 50569 |                 |

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 92%             |
| Children       | 84%             |
| Pedestrian     | 68%             |
| Safety systems | 66%             |
| Overall rating | 83%             |
| Video          | see crash video |



## Dimensions & weight

| Width               | 1760 mm |
|---------------------|---------|
| Height              | 1515 mm |
| Length              | 4245 mm |
| Wheel base          | 2600 mm |
| Kerb weight         | 1335 kg |
| Max. allowed weight | 1805 kg |

# Additional information

| Fuel tank capacity                | 50 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 11/11          |

**Engine number** 

1ZRU845210