





report date: 2024-03-29

General information

Make	MAZDA
Model	2 SPORT NAV
Colour	Blue
Year of manufacture	2017
Top speed	110 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	89 BHP
Max. torque	148 Nm at 4.000 rpm
Engine capacity	1.496 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 2

Date 2021-07-18

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-16
Pictures	50

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-09-26
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	13
Total items failed	0

MOT #6	2023-09-20 12:55	
MOT test number	794986705917	
Result	✓ Passed	
Next expiry date	2024-09-26	
Advice Offside Rear Tyre slightly damaged/cracking or perishing Heavily perished outer sidewall. Recommend new (5.2.3 (d) (ii))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing Heavily perished outer sidewall. Recommend new (5.2.3 (d) (ii))		
Advice Items removed from driver's view prior to test		

MOT #5		2022-09-27 15:43
MOT test	number	219668898902
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2022-09-27 07:59

MOT test number 618172471654

Result X Failed

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Bald inner edge (5.2.3 (d) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Bald inner edge (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2021-06-23 10:25

MOT test number 105469259106

Result
✓ Passed

Advice Offside Front Nail in tyre

Advice Offside Rear Nail in tyre

Advice All tyres perished

MOT #2 2020-07-01 12:04

MOT test number 946399090342

Result \square Passed

MOT #1 2020-06-29 14:00

MOT test number 208932858863

Result X Failed

MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



funder scincole

HW170BL

report date: 2024-03-29

More info >

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MAZDA had different number plates.

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-23
Last registration	2023-09-20
Complete history	See info



Registration #1	2017-03-23	13 mi
Registration #2	2020-06-29	14.633 mi
Registration #3	2020-07-01	14.633 mi
Registration #4	2021-06-23	16.827 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	86%
Children	78%
Pedestrian	84%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1495 mm
Length	4060 mm
Wheel base	2570 mm
Kerb weight	1075 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	44
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	P5 20 403130

CarCheck.co.uk page 11/11