



report date: 2024-03-28

General information

Make	KIA
Model	NIRO 3
Colour	Black
Year of manufacture	2018
Top speed	101 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	104 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.580 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	74.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	74.3 mpg
CO2 emission	29 g/km
CO2 label	A





Internet history

Entry 3

Date	2021-08-23
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

Entry 2

Date	2021-08-13
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-13
Pictures	0
Listing price	<a href="#">View report</a>

source: [heycar.co.uk](#)



MOT history

MOT expiry date	2024-10-07
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #5	2023-09-19 08:47
MOT test number	196468700434
Result	✓ Passed
Next expiry date	2024-10-07

MOT #4	2022-09-16 08:02
MOT test number	563974733054
Result	✓ Passed

MOT #3	2021-10-08 15:05
MOT test number	286570931515
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #2	2021-10-07 16:15
MOT test number	839181125082
Result	✗ Failed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
Advice	Nearside Front Nail in tyre
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1	2021-02-22 11:17
MOT test number	698049595931
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
7 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	7 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	B
<b>First licence fee (12 months)</b>	£ 0,00,-
<b>Standard rate (12 months)</b>	£ 170,00,-
<b>Standard rate (6 months)</b>	£ 93,50,-
<b>Premium rate (12 months)</b>	£ 560,00,-
<b>Premium rate (6 months)</b>	£ 308,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>LF18AUY</b>
Plate since	2019-09-29
Current registration	<b>LF18AUY</b>
Plate since	2019-09-29

More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-02
Last registration	2023-09-19
Complete history	<a href="#">See info</a>



Registration #1	2018-03-02	6 mi
Registration #2	2021-02-22	22.018 mi
Registration #3	2023-09-19	22.018 mi
Registration #4	2023-09-19	22.018 mi
Registration #5	2023-09-19	22.018 mi
Registration #6	2023-09-19	22.018 mi
Registration #7	2023-09-19	22.018 mi
Registration #8	2023-09-19	22.018 mi
Registration #9	2023-09-19	22.018 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	80%
Pedestrian	70%
Safety systems	81%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1805 mm
Height	1545 mm
Length	4355 mm
Wheel base	2700 mm
Kerb weight	1651 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4LEHS253232