




report date: 2024-03-28

General information

Make	NISSAN
Model	350 Z V6
Colour	Black
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	276 BHP
Max. torque	363 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	17.1 mpg
Consumption extra urban	31.7 mpg
Consumption combined	24.1 mpg
CO2 emission	280 g/km
CO2 label	M





Internet history

Entry 2


Date	2022-12-31
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-05
Pictures	4
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-19
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	35
Total items failed	13

MOT #21	2024-04-20 09:30
MOT test number	840154431721
Result	✓ Passed
Next expiry date	2025-04-19
Advice	Front to rear surface corrosion

MOT #20	2022-07-08 15:40
MOT test number	562942929431
Result	✓ Passed

MOT #19	2021-07-12 12:04
MOT test number	139084523247
Result	✓ Passed

MOT #18	2021-07-10 11:46
MOT test number	973899831928
Result	✗ Failed
Fail	Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Central Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #17** 2020-12-11 16:35**MOT test number** 444151845363**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Crossmember heavily corroded**MOT #16** 2019-12-10 13:26**MOT test number** 809437292679**Result** ✓ Passed**Advice** Centre floor crossmember corroded**MOT #15** 2019-12-09 11:26**MOT test number** 514313545403**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases snapped (6.1.2 (a))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Centre floor crossmember corroded**MOT #14** 2018-12-06 08:45**MOT test number** 218822935068**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Heat shields on exhaust loose

**MOT #13**

2018-12-06 08:45

MOT test number

839901388762

Result**✗ Failed****Pass with rectification**

Nearside Headlamp aim so that beam "kick up" is not visible on the screen

(4.1.2 (a))

Pass with rectification

Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Heat shields on exhaust loose

Pass with rectification

Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

MOT #12

2017-12-05 08:45

MOT test number

379496717733

Result**✓ Passed****Advice**

Exhaust heat shields corroded

Advice

Nearside Headlamp damaged but light output not reduced (1.7.5a)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Rear Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Headlamp damaged but light output not reduced (1.7.5a)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)

MOT #11

2016-12-09 08:54

MOT test number

250838947341

Result**✓ Passed****Advice**

Central Exhaust has a minor leak of exhaust gases (7.1.2)

Advice

Front Exhaust has a minor leak of exhaust gases (7.1.2)

Advice

Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #10** 2015-12-07 12:31**MOT test number** 581032094417**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2015-12-07 09:47**MOT test number** 460716914422**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases box (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-12-04 08:59**MOT test number** 358008634337**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-12-04 08:59**MOT test number** 489108934400**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-11-19 12:53**MOT test number** 559883023315**Result** ✓ Passed**MOT #5** 2012-12-14 09:21**MOT test number** 168759342302**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-11-21 16:04**MOT test number** 109715321357**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-11-08 12:29**MOT test number** 402632010420**Result** ✓ Passed**MOT #2** 2009-11-12 12:08**MOT test number** 861946019383**Result** ✓ Passed



MOT #1	2008-06-06 11:06
MOT test number	470338558128
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-05-12
Last registration	2024-04-20
Complete history	See info



Registration #1	2005-05-12	14 mi
Registration #2	2008-06-06	19.012 mi
Registration #3	2009-11-12	30.318 mi
Registration #4	2010-11-08	35.593 mi
Registration #5	2011-11-21	41.736 mi
Registration #6	2012-12-14	49.698 mi
Registration #7	2013-11-19	52.287 mi
Registration #8	2014-12-04	62.742 mi
Registration #9	2015-12-07	73.873 mi
Registration #10	2015-12-07	73.873 mi
Registration #11	2016-12-09	83.242 mi
Registration #12	2017-12-05	91.564 mi
Registration #13	2018-05-20	91.564 mi
Registration #14	2018-05-20	91.564 mi
Registration #15	2018-05-20	91.564 mi
Registration #16	2018-05-20	91.564 mi
Registration #17	2018-05-20	91.564 mi
Registration #18	2018-05-20	91.564 mi
Registration #19	2018-05-20	91.564 mi
Registration #20	2018-05-20	91.564 mi
Registration #21	2018-05-20	91.564 mi
Registration #22	2018-05-20	91.564 mi
Registration #23	2018-05-20	91.564 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1330 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1644 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	418568