



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 HDI S
Colour	Black
Year of manufacture	2009
Top speed	103 mph
0 - 60 mph	14.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	76.4 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-05-24
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-26
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	37
Total items failed	19

MOT #20 2023-11-27 13:57

MOT test number 444852429224

Result ✓ Passed

Next expiry date 2024-11-26

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19 2023-11-24 14:42

MOT test number 858107492208

Result ✗ Failed

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Rear Nail in tyre

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #18**

2022-10-29 13:42

MOT test number

460339507234

Result

✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #17

2022-10-28 11:37

MOT test number

123226693105

Result

✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16

2021-10-26 08:52

MOT test number

454592676460

Result

✓ Passed

- Advice** Rear Tyre worn close to legal limit/worn on edge both sides and splitting (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2021-10-26 08:52**MOT test number** 810867622512**Result** ✗ Failed**Pass with rectification** Front Position lamp not working both (4.2.1 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge both sides and splitting (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2020-08-25 16:53**MOT test number** 489096547633**Result** ✓ Passed**MOT #13** 2020-08-25 16:14**MOT test number** 650436274964**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #12** 2019-07-10 14:31**MOT test number** 950685816655**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2019-07-10 11:18

MOT test number

291451265971

Result**✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Rear Exhaust system insecure (6.1.2 (a))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2018-07-12 13:57

MOT test number

519414001175

Result**✓ Passed****Minor** Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning high level brake (4.3.1 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9**

2018-07-03 15:48

MOT test number

221755528249

Result

✗ Failed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))
- Fail** Offside Rear Brake hose excessively damaged (1.1.12 (b) (ii))
- Fail** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords + 2 mm 185 65 15 (5.2.3 (d) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning high level brake (4.3.1 (a) (i))
- Fail** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

MOT #8

2017-07-04 10:50

MOT test number

260593158959

Result

✓ Passed

- Advice** Nearside Rear uneven wear + outer edge close to the limit
- Advice** Nearside Rear reg plate light cover missing

MOT #7

2016-06-17 14:52

MOT test number

164851205114

Result

✓ Passed

- Advice** Nearside Rear reg plate light cover missing
- Advice** Nearside Rear tire uneven wear

**MOT #6** 2015-06-22 10:59**MOT test number** 856193775135**Result** ✓ Passed**Notice** Front wiper blades leaving smears**MOT #5** 2015-06-22 10:59**MOT test number** 529223175161**Result** ✗ Failed**Pass with rectification** Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Front wiper blades leaving smears**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2014-06-20 11:26**MOT test number** 558911674167**Result** ✓ Passed**Notice** Oil leak**MOT #3** 2013-07-04 10:41**MOT test number** 209485183172**Result** ✓ Passed**MOT #2** 2012-09-05 09:18**MOT test number** 928229642264**Result** ✓ Passed**MOT #1** 2012-09-05 09:18**MOT test number** 308279242454**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
26 November 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	26 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	FL59KRU
Plate since	2024-03-29
Current registration	FL59KRU
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-09-30
Last registration	2023-11-27
Complete history	See info



Registration #1	2009-09-30	13 mi
Registration #2	2012-09-05	31.952 mi
Registration #3	2013-07-04	38.566 mi
Registration #4	2014-06-20	50.767 mi
Registration #5	2015-06-22	65.613 mi
Registration #6	2016-06-17	76.659 mi
Registration #7	2017-07-04	87.730 mi
Registration #8	2018-07-03	99.427 mi
Registration #9	2018-07-12	99.456 mi
Registration #10	2019-07-10	112.504 mi
Registration #11	2019-09-20	121.277 mi
Registration #12	2019-10-20	121.277 mi
Registration #13	2019-11-20	121.277 mi
Registration #14	2019-12-20	121.277 mi
Registration #15	2020-01-20	121.277 mi
Registration #16	2020-02-20	121.277 mi
Registration #17	2020-03-20	121.277 mi
Registration #18	2020-04-20	121.277 mi
Registration #19	2020-05-20	121.277 mi
Registration #20	2020-06-20	121.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1261 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FDAX2402683