



SA08WLG

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI
Colour	Silver
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-05
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-05
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	29
Total items failed	8

MOT #18	2024-01-05 13:02
MOT test number	189845657315
Result	✓ Passed
Next expiry date	2025-01-05
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17	2024-01-05 10:41
MOT test number	560099385281
Result	✗ Failed
Fail	Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16**

2023-01-06 13:30

**MOT test number**

141867023949

**Result**

✓ Passed

- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** General corrosion on underbody and suspension components
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Suspension component pin or bush slightly worn various front and rear (5.3.4 (a) (i))

**MOT #15**

2023-01-06 12:38

**MOT test number**

444179278574

**Result**

✗ Failed

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Suspension component pin or bush slightly worn various front and rear (5.3.4 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** General corrosion on underbody and suspension components

**MOT #14**

2021-12-13 11:45

**MOT test number**

678524874658

**Result**

✓ Passed

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #13** 2020-12-28 12:01**MOT test number** 828094000461**Result** ✓ Passed

**Advice** Nearside Front Steering rack has slight free play detected at steering wheel inner track rod (2.3 (a) (i))

**MOT #12** 2020-12-28 09:53**MOT test number** 302836427083**Result** ✗ Failed

**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Fail** Offside Rear Wheel bearing play so excessive that directional control is impaired (5.1.3 (a) (ii))

**Advice** Nearside Front Steering rack has slight free play detected at steering wheel inner track rod (2.3 (a) (i))

**MOT #11** 2019-12-20 11:01**MOT test number** 806178733249**Result** ✓ Passed**MOT #10** 2018-12-21 13:22**MOT test number** 736597019711**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-12-19 10:26**MOT test number** 458747315484**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #8** 2017-12-28 10:56**MOT test number** 636802419135**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-12-30 10:43**MOT test number** 435612958009**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**MOT #6** 2015-12-30 15:37**MOT test number** 646616284777**Result** ✓ Passed

**MOT #5** 2014-12-23 14:16**MOT test number** 268287254312**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine/m/light staying on**MOT #4** 2014-01-04 10:24**MOT test number** 715264604041**Result** ✓ Passed**Notice** Rear tyres worn on inside edge**MOT #3** 2013-03-13 17:21**MOT test number** 947852073012**Result** ✓ Passed**MOT #2** 2012-03-14 10:31**MOT test number** 128184372479**Result** ✓ Passed**MOT #1** 2011-03-09 15:45**MOT test number** 347078161018**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
5 January 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	5 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>SA08WLG</b>
Plate since	2024-03-28
Current registration	 <b>SA08WLG</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-27
Last registration	2024-01-05
Complete history	<a href="#">See info</a>



Registration #1	2008-03-27	28 mi
Registration #2	2011-03-09	14.636 mi
Registration #3	2012-03-14	24.236 mi
Registration #4	2013-03-13	32.915 mi
Registration #5	2014-01-04	38.880 mi
Registration #6	2014-12-23	65.978 mi
Registration #7	2015-12-30	78.410 mi
Registration #8	2016-12-30	90.545 mi
Registration #9	2017-12-28	104.773 mi
Registration #10	2018-12-19	112.582 mi
Registration #11	2019-01-01	112.582 mi
Registration #12	2019-01-01	112.582 mi
Registration #13	2019-01-01	112.582 mi
Registration #14	2019-01-01	112.582 mi
Registration #15	2019-01-01	112.582 mi
Registration #16	2019-01-01	112.582 mi
Registration #17	2019-01-01	112.582 mi
Registration #18	2019-01-01	112.582 mi
Registration #19	2019-01-01	112.582 mi
Registration #20	2019-01-01	112.582 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 056163