





report date: 2024-03-29

### General information

Make	JAGUAR
Model	XK
Colour	Grey
Year of manufacture	2009
Top speed	155 mph
0 - 60 mph	5.3 seconds
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	385 BHP
Max. torque	515 Nm at 3.500 rpm
Engine capacity	5.000 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	25.2 mpg
CO2 emission	264 g/km
CO2 label	М



CarCheck.co.uk page 1/14



# Internet history

#### Entry 2

Date 2024-01-10

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-06-19
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-07-16
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	38
Total items failed	6

MOT #17		2023-07-17 15:02
MOT test	number	136389856230
Result		✓ Passed
Next exp	iry date	2024-07-16
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice	Advice Offside Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Rear suspension components are corroded		

CarCheck.co.uk page 3/14



MOT #16 2023-07-10 11:59

**MOT test number** 267599294478

Result × Failed

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Rear suspension components are corroded

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15 2022-06-10 12:18

**MOT test number** 452208264340

Result Passed

**Advice** Nearside Front Inner Tyre slightly damaged (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Nail in tyre

CarCheck.co.uk page 4/14



**MOT #14** 2022-06-06 12:04

**MOT test number** 339299706875

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Rear Nail in tyre

Advice Nearside Front Inner Tyre slightly damaged (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13 2021-06-22 14:31

**MOT test number** 325786436697

**Result** ✓ Passed

**MOT #12** 2021-02-12 13:16

**MOT test number** 508474164452

**Result** 
✓ Passed

**MOT #11** 2020-03-09 09:17

**MOT test number** 311436524612

**Result** ✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush front arm (5.3.4 (a) (i))

**MOT #10** 2019-03-08 15:20

**MOT test number** 916858029961

**Result** 
✓ Passed

CarCheck.co.uk page 5/14



MOT #9 2019-03-08 15:20

**MOT test number** 506935739465

**Result** X Failed

Pass with rectification Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #8 2018-03-15 11:02

**MOT test number** 623923763421

Result 

Passed

**Advice** Engine cover and undertray fitted

MOT #7 2018-03-06 10:56

**MOT test number** 632669105794

Result X Failed

Advice Engine cover and undertray fitted

**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

MOT #6 2017-03-07 13:00

**MOT test number** 630042221987

CarCheck.co.uk page 6/14



MOT #5		2016-01-25 11:12
MOT test	number	512138361794
Result		✓ Passed
Advice	Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (	8.3.1d)
Advice	Lower/Engine covers	
Advice	Exhaust backbox heatshield loose	
Advice	Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	
Advice	Both wiper blades split	

MOT #4		2015-02-05 13:50
MOT test	number	955736535093
Result		✓ Passed
Notice	Front tyres cracked	
Advice	Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Front tyres worn on inner edges	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8	8.3.1d)
Advice	Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	

MOT #3	2014-04-17 14:19
MOT test number	736317304178
Result	<b>✓</b> Passed
MOT #2	2013-04-10 10:56
MOT test number	347830903137
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/14



CE09EZJ

report date: 2024-03-29

 MOT #1
 2012-04-27 15:38

 MOT test number
 148968312183

 Result
 ✓ Passed

CarCheck.co.uk page 8/14




CE09EZJ

report date: 2024-03-29

#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e when miscory		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full is		λR
THE PARTY OF THE P		
***************************************		
*********		
***************************************		
	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



report date: 2024-03-29

#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-26
Last registration	2023-07-17
Complete history	See info



Registration #1	2009-03-26	18 mi
Registration #2	2012-04-27	13.381 mi
Registration #3	2013-04-10	21.582 mi
Registration #4	2014-04-17	31.100 mi
Registration #5	2015-02-05	38.559 mi
Registration #6	2016-01-25	44.894 mi
Registration #7	2017-03-07	49.788 mi
Registration #8	2018-03-06	51.660 mi
Registration #9	2018-03-15	51.694 mi
Registration #10	2019-03-08	52.306 mi
Registration #11		11.777 es
Registration #12		0.777-00
Registration #12 Registration #13		11.777 es
_		1.77 m
Registration #13		11.777 es 11.777 es 11.777 es
Registration #13 Registration #14		11.777 ea 11.777 ea 11.777 ea
Registration #13 Registration #14 Registration #15		11.77 mi 11.77 mi 11.77 mi 11.77 mi
Registration #13 Registration #14 Registration #15 Registration #16		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 13/14



		_		
- I ) Im	ension	с Х.	WAIG	nt.
	CHSIUH	3 W	weiu	III.

Width	1892 mm
Height	1329 mm
Length	4794 mm
Wheel base	2752 mm
Kerb weight	1696 kg
Max. allowed weight	2120 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	08112806062508PN

CarCheck.co.uk page 14/14