



General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Silver
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-15
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-24
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	18
Total items failed	10

MOT #20	2023-09-25 08:34
MOT test number	725531066168
Result	✓ Passed
Next expiry date	2024-10-24
Advice	Rear rear axle corroded

MOT #19	2022-10-24 12:33
MOT test number	538057877976
Result	✓ Passed

MOT #18	2022-10-17 08:21
MOT test number	274416290056
Result	✗ Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #17	2021-10-04 11:13
MOT test number	624091379678
Result	✓ Passed

MOT #16	2020-10-08 12:16
MOT test number	350206742605
Result	✓ Passed

**MOT #15** 2019-10-14 12:06**MOT test number** 354159248326**Result** ✓ Passed**Advice** Central Exhaust has a minor leak of exhaust gases centre sleeve slight blow (6.1.2 (a))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2019-10-14 11:37**MOT test number** 971207213110**Result** ✗ Failed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Central Exhaust has a minor leak of exhaust gases centre sleeve slight blow (6.1.2 (a))**Minor** Offside Front Tyre obviously under inflated (5.2.3 (l))**MOT #13** 2018-10-25 15:52**MOT test number** 900855374096**Result** ✓ Passed**MOT #12** 2018-01-30 13:00**MOT test number** 978486336288**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear coil spring corroded (2.4.C.1b)

**MOT #11** 2018-01-29 10:27**MOT test number** 927360225800**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #10** 2017-01-31 11:29**MOT test number** 614277794500**Result** ✓ Passed**MOT #9** 2016-02-02 15:19**MOT test number** 688574661847**Result** ✓ Passed**MOT #8** 2016-02-02 09:07**MOT test number** 472186852102**Result** ✗ Failed**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2015-02-05 15:00**MOT test number** 997876535096**Result** ✓ Passed

**MOT #6** 2013-07-31 13:45**MOT test number** 497282413239**Result** ✓ Passed**MOT #5** 2013-07-31 09:09**MOT test number** 648592413259**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #4** 2012-08-02 17:22**MOT test number** 996405712207**Result** ✓ Passed**Notice** Condensation in nearside side repeater not affecting performance**Notice** Spare wheel missing**MOT #3** 2012-08-02 17:22**MOT test number** 258575412276**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Condensation in nearside side repeater not affecting performance**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** Spare wheel missing**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #2** 2011-08-09 17:00**MOT test number** 658121221259**Result** ✓ Passed



MOT #1	2010-08-09 09:49
MOT test number	551591620280
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SD57AUP
Plate since	2024-03-29
Current registration	 SD57AUP
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-10-22
Last registration	2023-09-25
Complete history	See info



Registration #1	2007-10-22	20 mi
Registration #2	2010-08-09	10.760 mi
Registration #3	2011-08-09	14.890 mi
Registration #4	2012-08-02	17.460 mi
Registration #5	2013-07-31	18.807 mi
Registration #6	2013-07-31	18.807 mi
Registration #7	2015-02-05	22.245 mi
Registration #8	2016-02-02	24.131 mi
Registration #9	2016-02-02	24.131 mi
Registration #10	2017-01-31	26.964 mi
Registration #11	2018-01-31	26.964 mi
Registration #12	2018-01-31	26.964 mi
Registration #13	2018-01-31	26.964 mi
Registration #14	2018-01-31	26.964 mi
Registration #15	2018-01-31	26.964 mi
Registration #16	2018-01-31	26.964 mi
Registration #17	2018-01-31	26.964 mi
Registration #18	2018-01-31	26.964 mi
Registration #19	2018-01-31	26.964 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 375475