



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO EXPRESSION 16V
Colour	Blue
Year of manufacture	2004
Top speed	101 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-17
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-18
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	40
Total items failed	13

MOT #24 2024-01-19 08:38

MOT test number 416608839571

Result ✓ Passed

Next expiry date 2025-01-18

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #23 2024-01-18 15:45

MOT test number 303095860651

Result ✗ Failed

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Seat belt damaged (7.1.2 (b) (i))

MOT #22 2022-09-29 16:51

MOT test number 366535690719

Result ✓ Passed

**MOT #21** 2022-09-29 15:42**MOT test number** 692038048905**Result** ✗ Failed**Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #20** 2021-10-02 07:44**MOT test number** 818365083808**Result** ✓ Passed**MOT #19** 2021-10-01 11:49**MOT test number** 932114860022**Result** ✗ Failed**Fail** Offside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #18** 2020-09-17 10:57**MOT test number** 402853492018**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front fog lamp not working**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17**

2020-09-17 09:54

MOT test number

659331092482

Result**✗ Failed****Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front fog lamp not working**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16**

2019-09-04 09:43

MOT test number

666917353031

Result**✓ Passed****Advice** Nearside Front fog lamp not working**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15**

2019-09-04 09:43

MOT test number

946374991963

Result**✗ Failed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front fog lamp not working**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #14**

2018-09-05 14:55

MOT test number

696189721241

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Nearside Front Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #13**

2017-09-11 13:18

MOT test number

304029798147

Result**✓ Passed****Advice** Oil leak

**MOT #12**

2017-09-11 08:35

MOT test number

102421402422

Result**✗ Failed**

Advice Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Oil leak

Fail Offside Front coil spring broken (2.4.C.1a)

Advice Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Fail Nearside Front coil spring broken (2.4.C.1a)

Advice Exhaust slightly insecure

MOT #11

2016-09-08 07:59

MOT test number

497050787739

Result**✓ Passed****MOT #10**

2015-09-02 10:52

MOT test number

947775470864

Result**✓ Passed**

**MOT #9** 2014-09-17 09:30**MOT test number** 335440464458**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Exhaust rear silencer rubbers split.**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Rear tyres slightly perished**MOT #8** 2013-09-05 09:36**MOT test number** 375828843419**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2012-09-11 10:43**MOT test number** 588605552255**Result** ✓ Passed**MOT #6** 2011-09-06 15:44**MOT test number** 797629841287**Result** ✓ Passed**Notice** Front brake discs worn**MOT #5** 2010-09-21 12:11**MOT test number** 550314660273**Result** ✓ Passed**Notice** Front brake discs worn



MOT #4	2009-09-08 15:16
MOT test number	283161659210
Result	✓ Passed
MOT #3	2009-09-08 15:16
MOT test number	601201559272
Result	✗ Failed
<div>Pass with rectification</div> Nearside Front Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)	
MOT #2	2008-09-16 17:13
MOT test number	583860168245
Result	✓ Passed
MOT #1	2007-09-19 13:34
MOT test number	780002767290
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
18 January 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	OV54BYR
Plate since	2019-09-28
Current registration	OV54BYR
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-09-27
Last registration	2024-01-19
Complete history	See info



Registration #1	2004-09-27	20 mi
Registration #2	2007-09-19	11.057 mi
Registration #3	2008-09-16	14.615 mi
Registration #4	2009-09-08	17.726 mi
Registration #5	2010-09-21	21.378 mi
Registration #6	2011-09-06	23.611 mi
Registration #7	2012-09-11	25.599 mi
Registration #8	2013-09-05	27.170 mi
Registration #9	2014-09-17	28.905 mi
Registration #10	2015-09-02	29.826 mi
Registration #11	2016-09-08	30.198 mi
Registration #12	2017-09-11	30.655 mi
Registration #13	2017-09-11	30.655 mi
Registration #14	2018-09-05	31.378 mi
Registration #15	2019-09-02	32.198 mi
Registration #16	2020-09-02	33.018 mi
Registration #17	2021-09-02	33.838 mi
Registration #18	2022-09-02	34.658 mi
Registration #19	2023-09-02	35.478 mi
Registration #20	2024-01-19	36.298 mi
Registration #21	2024-01-19	36.298 mi
Registration #22	2024-01-19	36.298 mi
Registration #23	2024-01-19	36.298 mi
Registration #24	2024-01-19	36.298 mi
Registration #25	2024-01-19	36.298 mi



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2600 mm
Kerb weight	1120 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	50 l
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D009526