



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 SE
Colour	Blue
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-19
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-23
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	19
Total items failed	16

MOT #17	2023-10-23 11:31
MOT test number	625581172955
Result	✓ Passed
Next expiry date	2024-10-23

MOT #16	2022-10-24 15:11
MOT test number	666992212234
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2022-10-12 10:54

MOT test number

253565063872

Result**✗ Failed**

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14

2022-09-29 08:19

MOT test number

631447395394

Result**✗ Failed**

- Advice** Items removed from driver's view prior to test
- Fail** Offside Front Position lamp not working sidelight (4.2.1 (a) (ii))
- Fail** Offside Front Side repeater not working (4.4.1 (a) (ii))
- Minor** Rear Windscreen wiper blade defective split (3.4 (b) (i))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Rear Exhaust mounting defective snapped (6.1.2 (a))
- Advice** All rear passenger seats folded away unable to check rear seat belts fully
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Front Position lamp not working marker lamp (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2021-06-11 16:36**MOT test number** 716396554068**Result** ✓ Passed**Advice** Offside Front Coil spring worn (5.3.1 (b) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12** 2019-07-23 08:04**MOT test number** 430409309781**Result** ✓ Passed**MOT #11** 2019-07-22 11:12**MOT test number** 276161283196**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #10** 2018-10-31 16:07**MOT test number** 585145936259**Result** ✓ Passed**MOT #9** 2018-10-23 15:22**MOT test number** 669670447773**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases front flexi pipe (6.1.2 (a))**Fail** Fuel system component leaking excessively or a risk of fire pipe at rear of engine (6.1.3 (b) (ii))**Fail** Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #8** 2017-11-03 14:14**MOT test number** 574459933111**Result** ✓ Passed**Advice** BOTH O/S TYRES WEARING INNER EDGES HEAVILY**MOT #7** 2016-10-26 08:14**MOT test number** 469626166651**Result** ✓ Passed**MOT #6** 2015-11-11 16:05**MOT test number** 536282474162**Result** ✓ Passed**MOT #5** 2015-11-11 09:44**MOT test number** 593550177648**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #4** 2014-11-11 18:00**MOT test number** 987615814311**Result** ✓ Passed**MOT #3** 2013-11-12 10:26**MOT test number** 395766113355**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #2	2012-11-09 14:58
MOT test number	497964012303
Result	✓ Passed
<div>Notice Front o/s and n/s tyre inner edges badly worn</div>	

MOT #1	2011-11-12 09:13
MOT test number	666026911348
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
23 October 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-17
Last registration	2023-10-23
Complete history	See info



Registration #1	2008-11-17	21 mi
Registration #2	2011-11-12	22.405 mi
Registration #3	2012-11-09	31.814 mi
Registration #4	2013-11-12	41.419 mi
Registration #5	2014-11-11	51.480 mi
Registration #6	2015-11-11	61.058 mi
Registration #7	2015-11-11	61.060 mi
Registration #8	2016-10-26	70.402 mi
Registration #9	2017-11-03	79.750 mi
Registration #10	2018-10-23	90.474 mi
Registration #11	2019-10-23	99.999 mi
Registration #12	2020-10-23	109.999 mi
Registration #13	2021-10-23	119.999 mi
Registration #14	2022-10-23	129.999 mi
Registration #15	2023-10-23	139.999 mi
Registration #16	2024-10-23	149.999 mi
Registration #17	2025-10-23	159.999 mi
Registration #18	2026-10-23	169.999 mi
Registration #19	2027-10-23	179.999 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1530 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	363723