



SV07RZS

report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Grey
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-01-15
Pictures	2
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-01-29
Pictures	5
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT #19	2022-02-24 13:30
MOT test number	564267809364
Result	✓ Passed
Next expiry date	2023-02-23

MOT #18	2022-01-19 15:12
MOT test number	749773226511
Result	✗ Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Pass with rectification Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #17	2021-05-05 15:28
MOT test number	904158983991
Result	✓ Passed

Advice Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Rear Coil spring corroded Both sides (5.3.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Coil spring corroded (5.3.1 (b) (i))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #16	2019-11-26 11:31
MOT test number	634137101893
Result	✓ Passed

**MOT #15** 2019-01-08 15:06**MOT test number** 795965971954**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2018-01-03 13:15**MOT test number** 233428902162**Result** ✓ Passed**MOT #13** 2017-03-25 10:58**MOT test number** 637561963505**Result** ✓ Passed**MOT #12** 2017-03-25 10:58**MOT test number** 232374849031**Result** ✗ Failed**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #11** 2016-04-14 11:44**MOT test number** 733446346097**Result** ✓ Passed**Advice** Oil leak**Advice** Items removed from drivers view



MOT #102016-04-08 12:35

MOT test number917159333810

ResultX Failed

- Advice**Oil leak
- Fail**Front Exhaust has a major leak of exhaust gases (7.1.2)
- Advice**Items removed from drivers view
- Fail**Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail**Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail**Offside Front position lamp(s) not working (1.1.A.3b)

MOT #92015-03-26 17:27

MOT test number905895785017

Result✓ Passed

- Notice**Oil leak
- Advice**Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #8** 2015-03-26 10:39**MOT test number** 949635285074**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Oil leak**Fail** Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside Front front brake excessively fluctuating (3.7.B.3)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #7** 2014-03-29 15:27**MOT test number** 138708584033**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-04-16 15:55**MOT test number** 387156703112**Result** ✓ Passed

**MOT #5** 2013-04-16 13:39**MOT test number** 817176403140**Result** ✗ Failed**Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Fail** Offside Front coil spring incomplete (2.4.C.1a)**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #4** 2012-06-21 12:13**MOT test number** 755133072166**Result** ✓ Passed**MOT #3** 2012-06-14 12:00**MOT test number** 867546962162**Result** ✗ Failed**Fail** Offside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Both rear tyres outer walls cracked**Fail** Nearside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Bad oil leak at gearbox**MOT #2** 2011-05-30 10:31**MOT test number** 506710951196**Result** ✓ Passed



MOT #1	2010-06-03 12:32
MOT test number	384324650133
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	SV07RZS
Plate since	2019-09-29
Current registration	SV07RZS
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-28
Last registration	2022-02-24
Complete history	See info



Registration #1	2007-06-28	7 mi
Registration #2	2010-06-03	22.957 mi
Registration #3	2011-05-30	29.884 mi
Registration #4	2012-06-14	37.113 mi
Registration #5	2012-06-21	37.115 mi
Registration #6	2013-04-16	43.500 mi
Registration #7	2013-04-16	43.500 mi
Registration #8	2014-03-29	57.131 mi
Registration #9	2015-03-26	66.053 mi
Registration #10	2015-03-26	66.053 mi
Registration #11	2016-04-08	80.898 mi
Registration #12	2016-04-08	80.898 mi
Registration #13	2016-04-08	80.898 mi
Registration #14	2016-04-08	80.898 mi
Registration #15	2016-04-08	80.898 mi
Registration #16	2016-04-08	80.898 mi
Registration #17	2016-04-08	80.898 mi
Registration #18	2016-04-08	80.898 mi
Registration #19	2016-04-08	80.898 mi
Registration #20	2016-04-08	80.898 mi
Registration #21	2016-04-08	80.898 mi
Registration #22	2016-04-08	80.898 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4018117