



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO MULTIAIR LOUNGE
Colour	Blue
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-26
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-12
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	14
Total items failed	6

MOT #15	2024-04-08 09:54
MOT test number	899321033983
Result	✓ Passed
Next expiry date	2025-04-12

MOT #14	2024-04-08 09:54
MOT test number	216876487821
Result	✗ Failed
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #13	2023-04-13 12:07
MOT test number	394869812806
Result	✓ Passed

MOT #12	2023-04-13 12:07
MOT test number	530627329054
Result	✗ Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #11	2022-04-13 09:37
MOT test number	625616122126
Result	✓ Passed



MOT #10	2021-03-05 18:08
MOT test number	944879089468
Result	✓ Passed
Advice	Rear Coil spring corroded bothsides (5.3.1 (b) (i))
Advice	Rear exhaust outer caseing breaking up.

MOT #9	2021-03-05 10:00
MOT test number	746907582183
Result	✗ Failed
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Rear exhaust outer caseing breaking up.
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened bothsides (1.1.14 (a) (ii))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Rear Coil spring corroded bothsides (5.3.1 (b) (i))

MOT #8	2020-03-06 16:49
MOT test number	889714440478
Result	✓ Passed
Advice	Rear exhaust box outer skin corroded

MOT #7	2020-03-06 11:12
MOT test number	748971329907
Result	✗ Failed
Advice	Rear exhaust box outer skin corroded
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6** 2019-03-05 16:40**MOT test number** 864841306901**Result** ✓ Passed**Advice** Front Tyre slightly damaged/cracking or perishing both between treads (5.2.3 (d) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #5** 2018-07-11 14:36**MOT test number** 912706222902**Result** ✓ Passed**MOT #4** 2018-07-11 14:36**MOT test number** 106906749048**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #3** 2017-09-15 16:51**MOT test number** 343456949854**Result** ✓ Passed**Advice** Rear exhaust deteriorated**MOT #2** 2016-09-16 14:05**MOT test number** 829251342534**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-09-24 09:15**MOT test number** 193498924285**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 April 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-28
Current registration	XXXX XX
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-30
Last registration	2024-04-08
Complete history	See info



Registration #1	2012-09-30	29 mi
Registration #2	2015-09-24	22.094 mi
Registration #3	2016-09-16	34.122 mi
Registration #4	2017-09-15	46.243 mi
Registration #5	2018-07-11	56.206 mi
Registration #6	2018-07-11	56.206 mi
Registration #7	2019-03-05	58.106 mi
Registration #8	2020-03-06	63.110 mi
Registration #9	2020-03-06	63.110 mi
Registration #10	2020-03-06	63.110 mi
Registration #11	2020-03-06	63.110 mi
Registration #12	2020-03-06	63.110 mi
Registration #13	2020-03-06	63.110 mi
Registration #14	2020-03-06	63.110 mi
Registration #15	2020-03-06	63.110 mi
Registration #16	2020-03-06	63.110 mi
Registration #17	2020-03-06	63.110 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1075 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1711723