





report date: 2024-03-28

General information

Make	MINI
Model	PACEMAN COOPER
Colour	Blue
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2021-10-03

Pictures 49

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-02
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-26
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	12
Total items failed	5

MOT #9	2024-01-27 10:57	
MOT test number	327887196966	
Result	✓ Passed	
Next expiry date	2025-01-26	
Advice Nearside Front Tyre worn close to legal limit/worn on edge Close to wear indicators, perished, cuts and scrubbed off on outer edge (5.2.3 (e))		
Minor Windscreen damaged but not adversely affecting driver's view Chips (3.2 (a) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge Close to wear indicators, perished, cuts and scrubbed off on outer edge (5.2.3 (e))		

MOT #8	2024-01-19 11:55	
MOT test number	684387817811	
Result	× Failed	
Minor Windscreen damaged but not adversely affecting driver's view Chips (3.2 (a) (i))		
Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))		
Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))		
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge Close to wear indicators, perished, cuts and scrubbed off on outer edge (5.2.3 (e))		
Fail Offside Parking brake inoperative on one side (1.4.1 (a))		
Pass with rectification Offside Headlamp aim too low (4.1.2 (a))		
Advice Offside Front Tyre worn close to legal limit/worn on edge Close to wear indicators, perished, cuts and scrubbed off on outer edge (5.2.3 (e))		

CarCheck.co.uk page 3/12



MOT #6

MOT test number

LD63GBF

report date: 2024-03-28

2021-09-13 11:30

447830166984

MOT #7	2023-01-24 14:51
MOT test number	160637240029
Result	✓ Passed
Minor Windscreen wiper blade defective Both smeary (3.4 (b) (i)) Minor Windscreen damaged but not adversely affecting driver's view Chips (3.2 (a) (i))	

Result		✓ Passed
MOT #5		2020-09-14 07:18
MOT test	number	336321666538
Result		✓ Passed
MOT #4		2019-12-13 09:47
MOT test	number	997503856789
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2018-12-08 10:21
MOT test number	345160496752
Result	√ Passed
MOT #2	2017-12-11 13:09
MOT test number	366701053845
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/12



LD63GBF report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	26 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MINI had different number plates. ober of plates faste since

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-11-12
Last registration	2024-01-27
Complete history	See info



Registration #1	2013-11-12	28 mi
Registration #2	2016-12-14	30.115 mi
Registration #3	2017-12-11	35.618 mi
Registration #4	2018-12-08	42.027 mi
Registration #5	2019-12-13	48.673 mi
Registration #6	2020-09-14	56.754 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	B202J438 page 12/12