

Ford



# General information

Make	FORD
Model	FIESTA ZETEC TDCI
Colour	White
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	47.9 mpg



Ε	Ν	5	9	G	jХ	V	V
	rep	oort	da	te:	2024	1-03	-28

# MOT historyMOT #122021-01-14 13:17MOT test number596675926115Result✓ PassedNext expiry date2022-01-18

MOT #11	2020-01-17 15:53
MOT test number	552297980483
Result	✓ Passed

MOT #10	2020-01-17 09:22
MOT test number	625323852220
Result	🗙 Failed
<b>Fail</b> Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #9	2019-01-15 16:43
MOT test number	518470014967
Result	✓ Passed
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #8	2019-01-15 15:35
MOT test number	855258077827
Result	🗙 Failed
Fail Offside Headlamp aim too low (4.1.2 (a))	
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	

MOT #7	2018-01-19 13:35
MOT test number	192090160112
Result	✓ Passed



MOT #6	2018-01-18 09:21
MOT test number	117037472642
Result	🗙 Failed
Advice Front brake discs pitted and corroded	
<b>Fail</b> Rear Exhaust has a major leak of exhaust gases (7.1.2)	

MOT #5	2017-01-17 11:43
MOT test number	768993829692
Result	✓ Passed

МОТ #4	2016-01-12 13:19
MOT test number	947815866615
Result	✓ Passed
AdviceOffside Rear Tyre worn close to the legal limit (4.1.E.1)AdviceNearside Rear Tyre worn close to the legal limit (4.1.E.1)	

МОТ #3	2015-01-09 10:39
MOT test number	249769905067
Result	✓ Passed

MOT #2	2014-01-08 14:03
MOT test number	255098104026
Result	✓ Passed

MOT #1		2013-01-11 12:23
MOT test	number	499771213092
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

**EN59GXW** 

report date: 2024-03-28





## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		ARMP
Туре		
Damage 2		AMPLE
	E E	AT I
Date		*
Category	AMA	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





## Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





## Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-01-18
Last registration	2021-01-14
Complete history	See info



Registration #1	2010-01-18	9 mi
Registration #2	2013-01-11	14.705 mi
Registration #3	2014-01-08	23.101 mi
Registration #4	2015-01-09	33.535 mi
Registration #5	2016-01-12	43.191 mi
Registration #6	2017-01-17	48.853 mi
Registration #7	2018-01-18	54.979 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		10.307 mil





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

Number of axles CarCheck.co.uk

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1155 kg
Max. allowed weight	1550 kg
Additional information	
Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

2

**Engine number** 

9E23153