





report date: 2024-03-29

General information

Make	CITROEN
Model	DS4 E-HDI DSTYLE AIRDREAM
Colour	White
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	68.9 mpg
Consumption combined	64.2 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/13



Internet history

Entry 1


Date 2021-12-16

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2023-12-29
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	32
Total items failed	7

MOT #16	2022-12-30 16:34
MOT test number	545706596656
Result	✓ Passed
Next expiry date	2023-12-29

MOT #15	2022-12-30 1	4:48
MOT test number	er 590508961	849
Result	X Fa	iled
MAJOR Offsic	de Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1	(b)
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #14	2021-12-22 16:19
MOT test number	882477582951
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #13 2021-12-20 13:43

MOT test number 756920705272

Result X Failed

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

DANGEROUS Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Nail in tyre

MOT #12 2020-12-15 08:27

MOT test number 917176437209

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Direction indicator slightly discoloured both rear (4.4.3 (a))

MOT #11 2020-12-14 12:23

MOT test number 533866885983

Result × Failed

DANGEROUS Nearside Front Brake pad(s) missing pad material no longer attached to pad backing (1.1.13 (c))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Brake performance not tested (1.2.1 (g))

Advice Rear Direction indicator slightly discoloured both rear (4.4.3 (a))

CarCheck.co.uk page 4/13



MOT #10

YR61YPK
report date: 2024-03-29

2019-11-23 11:22

MOT test number 237765881984

Result ✓ Passed

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system

requires adjustment or repair. (1.2.1 (b) (i))

MOT #9 2018-11-28 16:44

MOT test number 211030922484

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Both top strut mountains creaking

MOT #8 2018-11-15 16:13

MOT test number 320548803089

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Both top strut mountains creaking

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #7 2017-11-30 15:18 MOT test number 382258023065

MOT #6 2017-10-25 11:51

MOT test number 455287096262

Result X Failed

Fail Offside Front Outer Front constant velocity joint is insecure (2.5.C.1b)

Fail Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Advise all four tyres on 3mm plus

Fail Nearside Front Headlamp insecure (1.7.3)

Advice Brake disc worn, pitted or scored, but not seriously weakened rear (3.5.1i)

MOT #5 2016-10-03 15:01

MOT test number 842794933517

Result ✓ Passed

MOT #4 2016-10-03 15:01

MOT test number 255874140639

Result × Failed

Pass with rectification Offside Rear Direction indicators incorrect colour (1.4.A.2f)

Pass with rectification Nearside Rear Direction indicators incorrect colour (1.4.A.2f)

MOT #3 2015-10-10 10:09

MOT test number 738972810089

CarCheck.co.uk page 6/13



report date: 2024-03-29

MOT #2 2014-10-27 10:10 **MOT test number** 817250504305 ✓ Passed Result MOT #1 2014-10-27 10:10 609100404314 **MOT test number X** Failed Result **Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d) Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-10-17
Last registration	2022-12-30
Complete history	See info



Registration #1	2011-10-17	24 mi
Registration #2	2014-10-27	29.485 mi
Registration #3	2015-10-10	41.128 mi
Registration #4	2016-10-03	50.599 mi
Registration #5	2016-10-03	50.599 mi
Registration #6	2017-10-25	64.998 mi
Registration #7	2017-11-30	66.660 mi
Registration #8	2018-11-15	71.789 mi
Registration #9	2018-11-28	71.918 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71.777 66
Registration #14		77.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBEH3025004

CarCheck.co.uk page 13/13