



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Red
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date 2021-06-04

Pictures 4

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-24
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	45
Total items failed	5

MOT #21	2024-03-25 16:05
MOT test number	405461276254
Result	✓ Passed
Next expiry date	2025-03-24

MOT #20	2024-03-22 14:01
MOT test number	797928736862
Result	✗ Failed
<p>MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))</p> <p>DANGEROUS Nearside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure side wall cracked (5.2.3 (d) (ii))</p> <p>MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))</p> <p>DANGEROUS Nearside Front Outer Tyre tread depth below requirements of 1.6mm edge (5.2.3 (e))</p>	

**MOT #19**

2023-06-29 07:14

MOT test number

263215543991

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #18

2023-06-27 11:45

MOT test number

184268324864

Result

✗ Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Minor Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MAJOR Exhaust system insecure (6.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MAJOR Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

MAJOR Emissions unable to be completed DUE TO BLOWING EXHAUST (8.2.1.2 (d))

**MOT #17**

2022-06-22 13:42

MOT test number

383569126469

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16

2022-06-21 10:04

MOT test number

707858497962

Result

✗ Failed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Front Windscreen washer not working (3.5 (a))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Emissions not tested (8.2.1.2 (d))
- DANGEROUS** Nearside Front Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- MAJOR** Central Front Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

MOT #15

2021-06-30 10:43

MOT test number

597291270725

Result

✓ Passed

**MOT #14** 2020-11-27 13:39**MOT test number** 143363193678**Result** ✓ Passed**MOT #13** 2020-11-27 10:55**MOT test number** 949883142002**Result** ✗ Failed**DANGEROUS** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #12** 2019-12-03 11:48**MOT test number** 634944914053**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2018-11-28 10:25**MOT test number** 918359610134**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2017-12-06 14:39**MOT test number** 248968660955**Result** ✓ Passed

**MOT #9** 2017-12-06 11:00**MOT test number** 235199789913**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #8** 2016-12-09 15:52**MOT test number** 847220799020**Result** ✓ Passed**MOT #7** 2016-12-09 14:55**MOT test number** 260942558658**Result** ✗ Failed**Fail** Rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2016-01-20 16:16**MOT test number** 974483384132**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases flexi (7.1.2)**MOT #5** 2015-01-19 13:40**MOT test number** 587749115072**Result** ✓ Passed**MOT #4** 2014-02-03 09:22**MOT test number** 839534334019**Result** ✓ Passed



MOT #3	2013-02-11 17:04
MOT test number	108232343462
Result	✓ Passed
<div>NoticeUnder-trays fitted obscuring some underside components</div>	

MOT #2	2012-02-08 10:38
MOT test number	715579932022
Result	✓ Passed

MOT #1	2012-02-08 10:38
MOT test number	147589532026
Result	✗ Failed
<div>Pass with rectificationNearside Headlamp aim too low (1.8)</div> <div>Pass with rectificationOffside Headlamp aim too low (1.8)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SK09LKO
Plate since	2019-06-29
Current registration	 SK09LKO
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-03-04
Last registration	2024-03-25
Complete history	See info



Registration #1	2009-03-04	18 mi
Registration #2	2012-02-08	22.585 mi
Registration #3	2013-02-11	30.074 mi
Registration #4	2014-02-03	36.582 mi
Registration #5	2015-01-19	44.133 mi
Registration #6	2016-01-20	49.361 mi
Registration #7	2016-12-09	51.947 mi
Registration #8	2016-12-09	51.947 mi
Registration #9	2017-12-06	55.031 mi
Registration #10	2017-12-06	55.035 mi
Registration #11	2018-11-28	58.103 mi
Registration #12	2019-05-29	59.277 mi
Registration #13	2019-05-29	59.277 mi
Registration #14	2019-05-29	59.277 mi
Registration #15	2019-05-29	59.277 mi
Registration #16	2019-05-29	59.277 mi
Registration #17	2019-05-29	59.277 mi
Registration #18	2019-05-29	59.277 mi
Registration #19	2019-05-29	59.277 mi
Registration #20	2019-05-29	59.277 mi
Registration #21	2019-05-29	59.277 mi
Registration #22	2019-05-29	59.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629