



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Blue
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-09-03
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-02
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-29
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	12
Total items failed	5

MOT #19	2023-08-29 15:25
MOT test number	851829370083
Result	✓ Passed
Next expiry date	2024-08-29

MOT #18	2023-08-29 09:54
MOT test number	153533900025
Result	✗ Failed
MAJOR	Rear Rear fog lamp not working (4.5.1 (a) (ii))
MAJOR	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #17	2022-08-08 13:16
MOT test number	410223319014
Result	✓ Passed

MOT #16	2022-08-08 07:43
MOT test number	502753910208
Result	✗ Failed
MAJOR	Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #15** 2021-08-11 11:30**MOT test number** 234620055313**Result** ✓ Passed**MOT #14** 2020-08-13 09:29**MOT test number** 456781811007**Result** ✓ Passed**MOT #13** 2020-08-13 09:29**MOT test number** 575973191382**Result** ✗ Failed

Pass with rectification Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))

Pass with rectification Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Pass with rectification Offside Rear fog lamp adversely affected by the operation of another lamp (4.5.4 (b))

MOT #12 2019-08-19 10:22**MOT test number** 143856155411**Result** ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2018-08-17 11:41**MOT test number** 104301371592**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2017-08-12 11:52**MOT test number** 845172467990**Result** ✓ Passed**MOT #9** 2017-08-12 09:20**MOT test number** 734515285992**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #8** 2016-08-30 12:51**MOT test number** 567949973458**Result** ✓ Passed**MOT #7** 2015-08-26 10:18**MOT test number** 760246357912**Result** ✓ Passed**MOT #6** 2014-04-22 16:24**MOT test number** 399192414163**Result** ✓ Passed**MOT #5** 2012-06-07 17:24**MOT test number** 768839152197**Result** ✓ Passed

**MOT #4** 2012-06-07 16:15**MOT test number** 487749252181**Result** ✗ Failed**Fail** Nearside Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Nail in nearside rear tyre**MOT #3** 2011-08-17 09:29**MOT test number** 276869521297**Result** ✓ Passed**MOT #2** 2010-08-11 15:31**MOT test number** 440183220237**Result** ✓ Passed**MOT #1** 2009-08-19 10:28**MOT test number** 622381539258**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
29 August 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2024-03-29
Current registration	 VAUXH
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-01
Last registration	2023-08-29
Complete history	See info



Registration #1	2006-09-01	7 mi
Registration #2	2009-08-19	20.062 mi
Registration #3	2010-08-11	25.335 mi
Registration #4	2011-08-17	30.865 mi
Registration #5	2012-06-07	33.518 mi
Registration #6	2012-06-07	33.518 mi
Registration #7	2014-04-22	39.374 mi
Registration #8	2015-08-26	39.435 mi
Registration #9	2016-08-30	41.220 mi
Registration #10	2017-08-12	42.858 mi
Registration #11	2017-08-12	42.859 mi
Registration #12	2019-05-29	51.277 mi
Registration #13	2019-05-29	51.277 mi
Registration #14	2019-05-29	51.277 mi
Registration #15	2019-05-29	51.277 mi
Registration #16	2019-05-29	51.277 mi
Registration #17	2019-05-29	51.277 mi
Registration #18	2019-05-29	51.277 mi
Registration #19	2019-05-29	51.277 mi
Registration #20	2019-05-29	51.277 mi
Registration #21	2019-05-29	51.277 mi
Registration #22	2019-05-29	51.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	19GK2653