



report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D4 BUSINESS EDITION
Colour	White
Year of manufacture	2015
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-08-19
Pictures	32
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-19
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #8	2024-04-20 12:08
MOT test number	877292562459
Result	✓ Passed
Next expiry date	2025-04-19
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 215/55/16 (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 215/55/16 (5.2.3 (e))

MOT #7	2024-04-15 08:21
MOT test number	434910721434
Result	✗ Failed
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 215/55/16 (5.2.3 (e))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 215/55/16 (5.2.3 (e))

**MOT #6** 2023-03-27 10:15**MOT test number** 625274765642**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5** 2022-04-04 15:48**MOT test number** 549283147366**Result** ✓ Passed**MOT #4** 2021-03-10 13:13**MOT test number** 868703794914**Result** ✓ Passed**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #3** 2020-03-10 16:31**MOT test number** 892197278977**Result** ✓ Passed**MOT #2** 2019-02-25 14:38**MOT test number** 574982015234**Result** ✓ Passed**Minor** Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #1** 2018-03-12 16:47**MOT test number** 900118482960**Result** ✓ Passed**Advice** Central Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 April 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	19 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-17
Last registration	2024-04-20
Complete history	See info



Registration #1	2015-03-17	22 mi
Registration #2	2018-03-12	70.119 mi
Registration #3	2019-02-25	92.122 mi
Registration #4	2020-03-10	112.228 mi
Registration #5	2021-03-10	122.366 mi
Registration #6	2022-03-10	132.504 mi
Registration #7	2023-03-10	142.642 mi
Registration #8	2024-03-10	152.780 mi
Registration #9	2025-03-10	162.918 mi
Registration #10	2026-03-10	173.056 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1606 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1159399