



report date: 2024-03-28

General information

Make	FIAT
Model	QUBO MULTIJET MYLIFE DUALOGIC
Colour	Blue
Year of manufacture	2012
Top speed	96 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-10-23
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-11-09
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	27
Total items failed	2

MOT #122023-11-22 14:07

MOT test number104390738517

Result	Failed
<p>MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))</p> <p>Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))</p> <p>MAJOR Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))</p> <p>Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))</p> <p>DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))</p> <p>MAJOR Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))</p> <p>Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))</p> <p>Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))</p> <p>MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))</p> <p>MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))</p> <p>Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))</p> <p>Advice Nearside Front Tyre worn close to legal limit/worn on edge bald on inside edge (5.2.3 (e))</p> <p>Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))</p>	

**MOT #11** 2022-10-26 10:27**MOT test number** 420764737952**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on inside edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively and corroded (1.1.14 (a) (i))**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on inside edge (5.2.3 (e))**Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2021-11-10 15:33**MOT test number** 433157037973**Result** ✓ Passed**MOT #9** 2021-11-10 15:33**MOT test number** 822384290406**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #8** 2021-06-18 09:47**MOT test number** 247888056006**Result** ✓ Passed**MOT #7** 2020-06-15 09:44**MOT test number** 669510215841**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #6** 2019-05-23 09:11**MOT test number** 334010387498**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2018-06-07 13:24**MOT test number** 320457575837**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #4** 2017-06-16 08:55**MOT test number** 635790844778**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-06-01 16:23**MOT test number** 271701022529**Result** ✓ Passed**MOT #2** 2016-06-01 09:53**MOT test number** 707484664712**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit D EVOID of primary tread (4.1.E.1)



MOT #1	2015-06-11 14:50
MOT test number	706662565186
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 December 2023

X

MOT

Expired:
9 November 2023

Tax status	Expired at 1 December 2023
Days left	151 days too late
MOT expiry date	9 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-07-27
Last registration	2023-11-22
Complete history	See info



Registration #1	2012-07-27	7 mi
Registration #2	2015-06-11	15.035 mi
Registration #3	2016-06-01	18.726 mi
Registration #4	2016-06-01	18.726 mi
Registration #5	2017-06-16	24.871 mi
Registration #6	2018-06-07	30.072 mi
Registration #7	2019-05-23	35.474 mi
Registration #8	2019-05-23	35.474 mi
Registration #9	2019-05-23	35.474 mi
Registration #10	2019-05-23	35.474 mi
Registration #11	2019-05-23	35.474 mi
Registration #12	2019-05-23	35.474 mi
Registration #13	2019-05-23	35.474 mi
Registration #14	2019-05-23	35.474 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1710 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4639928