



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SPORT TDI
Colour	Silver
Year of manufacture	2009
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	7.1 mpg
Consumption combined	5.5 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-26
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-08
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	35
Total items failed	0

MOT #14	2023-11-08 09:36
MOT test number	942721100965
Result	✓ Passed
Next expiry date	2024-11-08

MOT #13	2022-11-02 13:06
MOT test number	760911660820
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12	2022-10-31 09:24
MOT test number	776114912293
Result	✗ Failed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2021-11-09 12:31

MOT test number

657490136092

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10

2020-10-14 11:40

MOT test number

393413072691

Result

✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9

2020-10-10 12:34

MOT test number

470079767447

Result

✗ Failed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8

2019-10-13 13:35

MOT test number

854342329042

Result

✓ Passed

- Advice** No smoke detected by DSM

**MOT #7** 2018-10-10 10:02**MOT test number** 123021314759**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-10-29 14:44**MOT test number** 927376545220**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 235/45y17 (4.1.E.1)**Advice** Under trays fitted**Advice** No smoke detected by DSM**MOT #5** 2016-10-07 11:27**MOT test number** 261672458841**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 3 mm middle. (4.1.E.1)

**MOT #4** 2015-10-06 08:16**MOT test number** 957114586943**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened Inner braking surface (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened Inner braking surface (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-10-14 13:57**MOT test number** 349687384211**Result** ✓ Passed**MOT #2** 2013-10-15 15:07**MOT test number** 746398683219**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Nail in nearside front tyre
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #1 2012-10-23 16:50**MOT test number** 739147292213**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 November 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	YP59EEB
Plate since	2024-03-29
Current registration	YP59EEB
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-30
Last registration	2023-11-08
Complete history	See info



Registration #1	2009-10-30	20 mi
Registration #2	2012-10-23	18.906 mi
Registration #3	2013-10-15	23.311 mi
Registration #4	2014-10-14	26.624 mi
Registration #5	2015-10-06	29.271 mi
Registration #6	2016-10-07	30.857 mi
Registration #7	2017-10-29	34.836 mi
Registration #8	2018-10-10	40.679 mi
Registration #9	2019-10-20	45.377 mi
Registration #10	2020-10-20	50.377 mi
Registration #11	2021-10-20	55.377 mi
Registration #12	2022-10-20	60.377 mi
Registration #13	2023-10-20	65.377 mi
Registration #14	2024-10-20	70.377 mi
Registration #15	2025-10-20	75.377 mi
Registration #16	2026-10-20	80.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1411 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 013528