



General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Black
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption


Power	59 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1	
Date	2021-06-09
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-26
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	49
Total items failed	1

MOT #14	2024-01-19 15:42
MOT test number	836379929635
Result	✓ Passed
Next expiry date	2025-01-26

MOT #13	2023-01-11 16:48
MOT test number	448043111804
Result	✓ Passed

MOT #12	2022-01-18 17:08
MOT test number	385019650553
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has slight external damage to the casing plastic covers (5.3.2 (b))
Advice	Coolant leak
Advice	Offside Rear Shock absorbers has slight external damage to the casing plastic covers (5.3.2 (b))

**MOT #11** 2022-01-17 12:55**MOT test number** 533773297264**Result** ✗ Failed

- Advice** Coolant leak
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing plastic covers (5.3.2 (b))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing plastic covers (5.3.2 (b))

MOT #10 2021-01-27 10:59**MOT test number** 842733326684**Result** ✓ Passed

- Advice** Rear bump stops split
- Advice** Fuel cap seal perished
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #9 2019-12-02 15:40**MOT test number** 292642767777**Result** ✓ Passed

- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear Tyre worn to 3mm
- Advice** Front Exhaust has a minor leak of exhaust gases Exhaust flexible joint (6.1.2 (a))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Rear Bump stops deteriorated

**MOT #8** 2019-12-02 10:27**MOT test number** 180553869784**Result** ✗ Failed

- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases Exhaust flexible joint (6.1.2 (a))
- MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #7 2018-11-28 12:26**MOT test number** 911604551299**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn to 2mm (5.2.3 (e))
- Advice** Rear bump stops split
- Advice** Exhaust system corroded
- Advice** Both headlights slightly deteriorated

**MOT #6**

2017-11-23 09:37

MOT test number

233345104122

Result

✓ Passed

- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Front Brake discs slightly worn and corroded
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Both rear bump stops split
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5

2017-11-23 09:37

MOT test number

546751236807

Result

✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake discs slightly worn and corroded
- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Both rear bump stops split
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #4** 2016-12-19 11:53**MOT test number** 540419512454**Result** ✓ Passed

- Advice** Rear bump stops perished
- Advice** Exhaust system slightly corroded
- Advice** Nearside Rear bump stop split
- Advice** Rear tyres worn to 2.5mm

MOT #3 2015-11-10 17:02**MOT test number** 396487409143**Result** ✓ Passed

- Advice** FUEL CAP SEAL STARTING TO PERISH
- Advice** BOTH REAR TYRES STARTING TO PERISH

MOT #2 2014-11-11 10:08**MOT test number** 239635514385**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both front tyres and both rear tyres are perishing and cracking

MOT #1 2013-09-02 12:33**MOT test number** 135685743200**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
26 January 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	26 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	DE10NPC
Plate since	2024-03-29
Current registration	DE10NPC
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-10
Last registration	2024-01-19
Complete history	See info



Registration #1	2010-06-10	26 mi
Registration #2	2013-09-02	18.749 mi
Registration #3	2014-11-11	27.461 mi
Registration #4	2015-11-10	33.779 mi
Registration #5	2016-12-19	47.092 mi
Registration #6	2017-11-23	60.532 mi
Registration #7	2017-11-23	60.532 mi
Registration #8	2018-11-28	83.739 mi
Registration #9	2019-05-29	95.377 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Engine number	CGP 038843