



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 VTR PLUS HDI
Colour	Blue
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-29
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #12</b>	2021-10-19 09:24
<b>MOT test number</b>	472780985754
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-10-18

<b>MOT #11</b>	2020-10-08 08:16
<b>MOT test number</b>	789202146298
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2020-10-05 08:38
<b>MOT test number</b>	820866703312
<b>Result</b>	✗ Failed

- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

<b>MOT #9</b>	2019-11-09 15:25
<b>MOT test number</b>	851734988139
<b>Result</b>	✓ Passed

**MOT #8** 2019-11-09 13:42**MOT test number** 126117892513**Result** ✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #7** 2016-05-23 16:34**MOT test number** 817157389087**Result** ✓ Passed

- Advice** Item removed from drivers veiw
- Advice** O/s/r tyre worn on outer edge

**MOT #6** 2016-05-21 13:50**MOT test number** 832193961372**Result** ✗ Failed

- Advice** Item removed from drivers veiw
- Fail** Wheel nut(s) missing n/s/f (4.2.A.1e)
- Fail** Tyre tread depth below requirements of 1.6mm n/s/r 225/55/17/y (4.1.E.1)
- Advice** O/s/r tyre worn on outer edge
- Fail** Suspension arm has excessive play in a ball joint n/s/f (2.4.G.2)
- Fail** Wheel nut(s) missing o/s/f (4.2.A.1e)



MOT #5	2015-05-09 14:11
MOT test number	245759525424
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4	2015-05-09 11:28
MOT test number	688919425163
Result	✗ Failed
Fail	Nearside Stop lamp not working (1.2.1b)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #3** 2014-05-12 09:45**MOT test number** 386922634175**Result** ✓ Passed

- Notice** Nail in offside rear tyre
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Nail in nearside rear tyre
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2013-05-24 15:38**MOT test number** 958314843128**Result** ✓ Passed**MOT #1** 2012-03-09 14:26**MOT test number** 235499662033**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-03-27
Last registration	2021-10-19
Complete history	<a href="#">See info</a>



Registration #1	2009-03-27	16 mi
Registration #2	2012-03-09	40.774 mi
Registration #3	2013-05-24	22.110 mi
Registration #4	2014-05-12	43.421 mi
Registration #5	2015-05-09	66.737 mi
Registration #6	2015-05-09	66.737 mi
Registration #7	2016-05-21	87.117 mi
Registration #8	2016-05-21	87.117 mi
Registration #9	2016-05-21	87.117 mi
Registration #10	2016-05-21	87.117 mi
Registration #11	2016-05-21	87.117 mi
Registration #12	2016-05-21	87.117 mi
Registration #13	2016-05-21	87.117 mi
Registration #14	2016-05-21	87.117 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1853 mm
Height	1471 mm
Length	4829 mm
Wheel base	2750 mm
Kerb weight	1538 kg
Max. allowed weight	2178 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBN3000874