




report date: 2024-03-29

## General information

Make	VOLVO
Model	V60 D5 SE LUX
Colour	Black
Year of manufacture	2010
Top speed	143 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H



**MOT history**

<b>MOT expiry date</b>	2021-10-28
<b>MOT pass rate</b>	73 %
<b>MOT passed</b>	8
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	12
<b>Total items failed</b>	8

<b>MOT #11</b>	2020-10-08 14:26
<b>MOT test number</b>	558696766482
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-10-28
<b>Advice</b>	Non obligatory mirror damaged

<b>MOT #10</b>	2020-10-07 09:49
<b>MOT test number</b>	733721215278
<b>Result</b>	✗ Failed
<b>Advice</b>	Non obligatory mirror damaged
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

<b>MOT #9</b>	2019-10-29 14:59
<b>MOT test number</b>	249966368951
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2018-11-14 11:09**MOT test number** 248063753530**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge devoid of tread on inner edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**MOT #7** 2017-11-21 10:46**MOT test number** 624932461816**Result** ✓ Passed**MOT #6** 2017-11-20 09:32**MOT test number** 475966490107**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Side repeater not working (1.4.A.2c)**Fail** Offside Rear Tyre has ply or cords exposed inner edge (4.1.D.1b)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Tyre has ply or cords exposed inner edge (4.1.D.1b)**MOT #5** 2016-11-04 09:14**MOT test number** 772292070233**Result** ✓ Passed**MOT #4** 2015-11-16 16:35**MOT test number** 264952127479**Result** ✓ Passed**Advice** Front nearside and offside tyres worn on inner edges**Advice** Front wiper blades slightly smear screen



MOT #3	2015-11-16 12:19
MOT test number	194992307086
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Front brake discs lipped
Advice	Front nearside and offside tyres worn on inner edges
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Rear brake discs lipped
Advice	Front wiper blades slightly smear screen

MOT #2	2014-11-10 10:53
MOT test number	167504314339
Result	✓ Passed

MOT #1	2013-11-08 11:11
MOT test number	756252313338
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
28 February 2021

✕  
MOT

Expired:  
28 October 2021

Tax status	Expired at 28 February 2021
Days left	1157 days too late
MOT expiry date	28 October 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-11-30
Last registration	2020-10-08
Complete history	<a href="#">See info</a>



Registration #1	2010-11-30	17 mi
Registration #2	2013-11-08	27.906 mi
Registration #3	2014-11-10	40.937 mi
Registration #4	2015-11-16	54.320 mi
Registration #5	2015-11-16	54.323 mi
Registration #6	2016-11-04	65.570 mi
Registration #7	2019-10-20	75.277 mi
Registration #8	2019-10-20	75.277 mi
Registration #9	2019-10-20	75.277 mi
Registration #10	2019-10-20	75.277 mi
Registration #11	2019-10-20	75.277 mi
Registration #12	2019-10-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1674 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	901744