



General information

Make	MINI
Model	MINI COOPER S
Colour	Red
Year of manufacture	2010
Top speed	142 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	136 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT expiry date	2024-04-11
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	26
Total items failed	1

MOT #13 2023-04-12 12:34**MOT test number** 675868766528**Result** ✓ Passed**Next expiry date** 2024-04-11**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12** 2022-03-09 11:36**MOT test number** 348568630447**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2021-02-03 13:29**MOT test number** 508678514466**Result** ✓ Passed**Advice** All 4x alloy wheels slight buckles on inner edges

**MOT #10**

2020-03-06 09:53

MOT test number

101802433356

Result

✓ Passed

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**MOT #9**

2020-02-27 10:00

MOT test number

229627752130

Result

✗ Failed

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**DANGEROUS** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**DANGEROUS** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Offside Rear Upper Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #8**

2019-03-05 15:31

MOT test number

736450713433

Result

✓ Passed

**MOT #7** 2018-03-02 11:37**MOT test number** 348617061569**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2018-03-02 11:24**MOT test number** 519608129935**Result** ✗ Failed**Fail** Front registration plate insecure (6.3.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2017-02-24 12:00**MOT test number** 300423815598**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2016-02-17 11:01**MOT test number** 888863273829**Result** ✓ Passed**MOT #3** 2015-03-05 14:34**MOT test number** 318294365043**Result** ✓ Passed



MOT #2	2014-09-27 10:59
MOT test number	418150474224
Result	✓ Passed
MOT #1	2013-08-23 14:10
MOT test number	137505633285
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✗
MOT

Expired:
11 April 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	11 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-11-08
Last registration	2023-04-12
Complete history	See info



Registration #1	2010-11-08	6 mi
Registration #2	2013-08-23	20.204 mi
Registration #3	2014-09-27	26.628 mi
Registration #4	2015-03-05	27.430 mi
Registration #5	2016-02-17	48.698 mi
Registration #6	2017-02-24	62.705 mi
Registration #7	2018-03-02	73.482 mi
Registration #8	2018-03-02	73.483 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	B8571849