





report date: 2024-03-29

#### General information

Make	BMW
Model	640 435D XDRIVE M SPORT
Colour	White
Year of manufacture	-
Top speed	155 mph
0 - 60 mph	4.7 seconds
Gearbox	8 speed automatic

### Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg



CarCheck.co.uk page 1/10




## Internet history

#### Entry 2

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

#### Entry 1

Date	2021-01-29
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/10



#### **MOT** history

**MOT #5** 2020-11-11 13:57

**MOT test number** 616225212876

Result \( \sqrt{Passed} \)

Next expiry date 2021-11-13

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge worn inside edge (5.2.3 (e))

MOT #4 2020-11-09 09:59

MOT test number 477785609821

**Result** X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge worn inside edge (5.2.3 (e))

**DANGEROUS** Nearside Rear Tyre has ply or cords exposed 2753020 (5.2.3 (d) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2019-11-12 17:01

MOT test number 742935086884

Result \( \sqrt{Passed} \)

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Undertrays fitted underneath vehicle

**MOT #2** 2019-11-12 11:45

MOT test number 186203627524

**Result** X Failed

**DANGEROUS** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure inner edge of tyre (5.2.3 (d) (ii))

**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner edge of tyre (5.2.3 (d) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Undertrays fitted underneath vehicle

CarCheck.co.uk page 3/10



MOT #1 2018-11-09 15:26

**MOT test number** 817681704291

**Result** ✓ Passed

CarCheck.co.uk page 4/10



#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
THE PARTY OF THE P	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	UK NEZ
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2015-11-14
Last registration	2020-11-11
Complete history	See info



Registration #1	2015-11-14	6 mi
Registration #2	2018-11-09	44.183 mi
Registration #3	2019-11-12	55.341 mi
Registration #4	2019-11-12	55.341 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 9/10




## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1825 mm
Height	1392 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1625 kg
Max. allowed weight	2145 kg

## Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 10/10

Number of axles 2

**Engine number** 72159258