





report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO MULTIJET MYLIFE
Colour	Grey
Year of manufacture	2012
Top speed	102 mph
0 - 60 mph	13.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history


Entry 1

Date 2022-06-08

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



KN62EEU report date: 2024-03-28

MOT history

MOT expiry date	2024-06-15
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	26
Total items failed	3

MOT #12		2023-06-13 13:34
MOT test	number	942417978726
Result		✓ Passed
Next exp	iry date	2024-06-15
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteri	orated (6.1.7 (g) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Headlamp lens slightly defective both sides (4.1.1 (b) (i))	

CarCheck.co.uk page 3/13



MOT #11

Advice

Fail

Minor

KN62EEU

report date: 2024-03-28

2023-06-12 08:58

MOT test number

Result

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Headlamp lens slightly defective both sides (4.1.1 (b) (i))

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10 2022-06-16 09:54
MOT test number 270329170715
Result ✓ Passed

MOT #9 2022-06-15 12:24

MOT test number 590416117521

Result ★ Failed

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Minor

Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Minor

Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

MOT #7 2021-04-07 12:55 **MOT** test number 447519005948 Result ✓ Passed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Advice Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #6

MOT test number

728414688608

Result

Advice
Rear tyres wearing on inner edges

MOT #5

MOT test number

363773680539

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Exhaust has a minor leak of exhaust gases tail box (6.1.2 (a))

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4	2018-09-19 13:54
MOT test number	995788714462
Result	✓ Passed
MOT #3	2017-09-28 08:09
MOT test number	533398249895
Result	✓ Passed
MOT #2	2016-09-16 08:26
MOT test number	918861287820
Result	✓ Passed
MOT #1	2015-09-11 08:38
MOT test number	561770868974
Result	✓ Passed
Advice Front brake pads and discs wearing low	

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



KN62EEU report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



KN62EEU report date: 2024-03-28

Owner history

e inter instary	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
manus .	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	AIR.
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



KN62EEU report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-28
Last registration	2023-06-13
Complete history	See info



Registration #1	2012-09-28	15 mi
Registration #2	2015-09-11	35.312 mi
Registration #3	2016-09-16	53.993 mi
Registration #4	2017-09-28	73.638 mi
Registration #5	2018-09-19	85.685 mi
Registration #6	2019-09-17	98.893 mi
Registration #7	2020-04-09	105.517 mi
Registration #8		71.777 es
Registration #9		71.777 es
Registration #10		71.777 es
Registration #11		71.777 es
Registration #12		11.117 es
Registration #13		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Wheel base	2755 mm
Kerb weight	1410 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/3

Number of axles 2
Engine number 6796065