



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO POP
Colour	White
Year of manufacture	2013
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-29
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-12-14
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	21
Total items failed	12

MOT #14	2023-12-15 11:30
MOT test number	803585094435
Result	✓ Passed
Next expiry date	2024-12-14
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #13	2023-12-13 14:26
MOT test number	706069922065
Result	✗ Failed
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #12**

2022-05-17 08:37

MOT test number

973091446005

Result

✓ Passed

- Advice** Spare tyre defective cords exposed
- Advice** Clutch pedal rubber missing
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt both outer seats
- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. both axles (1.2.1 (b) (i))

MOT #11

2022-05-17 08:37

MOT test number

416729373068

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt both outer seats
- Pass with rectification** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Clutch pedal rubber missing
- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. both axles (1.2.1 (b) (i))
- Advice** Spare tyre defective cords exposed

MOT #10

2021-05-27 12:15

MOT test number

545582687411

Result

✓ Passed

**MOT #9** 2021-05-27 12:15**MOT test number** 636137786812**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2020-02-24 16:11**MOT test number** 818374954656**Result** ✓ Passed**Advice** Oil leak**MOT #7** 2019-02-21 10:21**MOT test number** 819251654838**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #6** 2019-02-21 10:21**MOT test number** 997251259164**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #5** 2018-03-09 13:53**MOT test number** 721152889922**Result** ✓ Passed

**MOT #4** 2018-03-09 13:42**MOT test number** 587396634999**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2017-02-09 16:24**MOT test number** 703658755712**Result** ✓ Passed**MOT #2** 2016-03-04 15:33**MOT test number** 727722140196**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Oil leak**MOT #1** 2016-03-04 14:21**MOT test number** 454247723659**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Oil leak**Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
14 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	14 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-03-07
Last registration	2023-12-15
Complete history	See info



Registration #1	2013-03-07	18 mi
Registration #2	2016-03-04	31.141 mi
Registration #3	2016-03-04	31.141 mi
Registration #4	2017-02-09	39.693 mi
Registration #5	2018-03-09	42.271 mi
Registration #6	2018-03-09	42.271 mi
Registration #7	2019-02-21	55.645 mi
Registration #8	2019-02-21	55.645 mi
Registration #9	2019-03-20	55.645 mi
Registration #10	2019-03-20	55.645 mi
Registration #11	2019-03-20	55.645 mi
Registration #12	2019-03-20	55.645 mi
Registration #13	2019-03-20	55.645 mi
Registration #14	2019-03-20	55.645 mi
Registration #15	2019-03-20	55.645 mi
Registration #16	2019-03-20	55.645 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	0596130