





report date: 2024-03-28

General information

Make	HYUNDAI
Model	AMICA CDX
Colour	Red
Year of manufacture	-
Top speed	91 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	97 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-18

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT #16	2020-10-09 10:21
MOT test number	716009158069
Result	✓ Passed
Next expiry date	2021-11-06
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #15	2019-11-05 12:11
MOT test number	683927277441
Result	✓ Passed
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #14		2018-10-18 14:27
MOT test	number	129189083184
Result		✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Temp. repair to exhaust front pipe	

MOT #13	2017-10-25 12:01
MOT test number	345925616421
Result	✓ Passed
Advice Temp. repair on exhaust	

CarCheck.co.uk page 3/12



Fail

DV06JCY report date: 2024-03-28

MOT #12 2017-10-19 16:27 791550263860 **MOT** test number Result × Failed Fail Nearside front brake binding (3.7.B.1) Fail Offside rear brake binding (3.7.B.1) Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) Fail Offside front brake binding (3.7.B.1) Fail Front Exhaust has a major leak of exhaust gases (7.1.2)

MOT #11

MOT test number

269415351943

Result

Advice Temp.repair to exhaust (minor blow)

Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

MOT #10

MOT test number

726293587762

Result

Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #9

MOT test number

Result

Notice All tyres wearing on inner edges

Notice Light cracking on outer sidewalls of rear tyres

CarCheck.co.uk page 4/12



Advice

MOT test number

DV06JCY report date: 2024-03-28

406328521205

MOT #8 2013-12-20 08:45 **MOT test number** 719454853390 Result ✓ Passed MOT #7 2013-12-17 12:13 **MOT** test number 568731753311 Result × Failed Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6	2012-08-22 17:07
MOT test number	836345432257
Result	✓ Passed
MOT #5	2011-08-16 16:28

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



MOT #4 2011-08-03 15:00 **MOT test number** 268075111269 Result ★ Failed Fail Nearside Front position lamp(s) not working (1.1.A.3b) Nearside Headlamp not working on dipped beam (1.7.5a) Fail **Advice** Nearside Rear Brake pipe slightly damaged (3.6.B.2c) Fail Offside Front position lamp(s) not working (1.1.A.3b) Fail Nearside Lower Stop lamp not working (1.2.1b) Notice Cut in offside front tyre tread

MOT #3	2010-09-16 13:39
MOT test number	450399850218
Result	✓ Passed
MOT #2	2009-03-13 13:40
MOT test number	772022279088
Result	✓ Passed
MOT #1	2009-03-13 09:02
MOT test number	442202979072
Result	X Failed
Fail Nearside Rear Braking system leaking (3.6.A.1)	

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
OWITCH	IIIJCOI y

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		NDAI
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	UK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-31
Last registration	2020-10-09
Complete history	See info



Registration #1	2006-03-31	12 mi
Registration #2	2009-03-13	23.743 mi
Registration #3	2009-03-13	23.743 mi
Registration #4	2010-09-16	435.875 mi
Registration #5	2011-08-03	41.270 mi
Registration #6	2011-08-16	41.358 mi
Registration #7	2012-08-22	46.807 mi
Registration #8	2013-12-17	51.659 mi
Registration #9	2013-12-20	51.724 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 mg

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	1007 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	G4HG6M794443

CarCheck.co.uk page 12/12