



RENAULT

HT56DDA

report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE VVT 111 SCENIC
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-08
Pictures	16
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #18	2021-07-08 10:16
MOT test number	340831669293
Result	✓ Passed
Next expiry date	2022-07-07
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

MOT #17	2021-07-08 10:16
MOT test number	293245445240
Result	✗ Failed
Advice	Nearside Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Pass with rectification	Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16	2020-11-02 15:42
MOT test number	443438053110
Result	✓ Passed
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Nearside Brake pipe corroded, covered in grease or other material Main pipe (1.1.11 (c))

**MOT #15**

2020-11-02 12:53

MOT test number

468707723646

Result

✗ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Play in steering rack inner joint(s)**Advice** Nearside Brake pipe corroded, covered in grease or other material Main pipe (1.1.11 (c))**MOT #14**

2019-10-24 12:53

MOT test number

210751143794

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Main pipe (1.1.11 (c))**MOT #13**

2019-10-21 11:31

MOT test number

138820427263

Result

✗ Failed

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Main pipe (1.1.11 (c))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Rear Service brake excessively fluctuating (1.2.1 (e))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #12** 2018-08-20 10:06**MOT test number** 888650448243**Result** ✓ Passed**MOT #11** 2017-09-15 12:05**MOT test number** 748355932888**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Under trays fitted**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** All road wheels have trim covers**MOT #10** 2017-09-12 08:59**MOT test number** 842251134949**Result** ✗ Failed**Advice** Under trays fitted**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** All road wheels have trim covers**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #9** 2016-09-09 15:27**MOT test number** 770240449834**Result** ✓ Passed



MOT #8	2015-09-10 12:57
MOT test number	390492039227
Result	✓ Passed
Advice	Wheel trims/Under trays fitted

MOT #7	2014-08-15 13:05
MOT test number	467507024238
Result	✓ Passed
Advice	Offside Steering system has slight free play detected at steering wheel (2.2.A.1b)

MOT #6	2014-08-15 13:05
MOT test number	415767224224
Result	✗ Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Advice	Offside Steering system has slight free play detected at steering wheel (2.2.A.1b)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)

MOT #5	2013-08-21 15:50
MOT test number	755923933297
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Both front steering rack ends play
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2012-08-17 14:46
MOT test number	178720332236
Result	✓ Passed
Advice	Offside Front Ball joint has slight play (2.2.B.1f)
Advice	Nearside Front Ball joint has slight play (2.2.B.1f)

MOT #3	2011-08-22 11:33
MOT test number	249484031234
Result	✓ Passed

MOT #2	2010-08-21 09:33
MOT test number	753853630235
Result	✓ Passed

MOT #1	2009-08-22 09:00
MOT test number	111814339210
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-02-08
Last registration	2021-07-08
Complete history	See info



Registration #1	2007-02-08	14 mi
Registration #2	2009-08-22	33.266 mi
Registration #3	2010-08-21	38.309 mi
Registration #4	2011-08-22	43.232 mi
Registration #5	2012-08-17	47.369 mi
Registration #6	2013-08-21	50.802 mi
Registration #7	2014-08-15	53.794 mi
Registration #8	2015-09-10	57.135 mi
Registration #9	2016-09-09	60.441 mi
Registration #10	2017-09-12	63.411 mi
Registration #11	2018-09-12	66.382 mi
Registration #12	2019-09-12	69.353 mi
Registration #13	2020-09-12	72.324 mi
Registration #14	2021-09-12	75.295 mi
Registration #15	2022-09-12	78.266 mi
Registration #16	2023-09-12	81.237 mi
Registration #17	2024-09-12	84.208 mi
Registration #18	2025-09-12	87.179 mi
Registration #19	2026-09-12	90.150 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1701 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D042546