




report date: 2024-03-29

General information

Make	VOLVO
Model	S80 D5 SE LUX
Colour	Green
Year of manufacture	-
Top speed	130 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg





Internet history

Entry 1

Date	2021-09-04
Pictures	14
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT #17	2021-02-16 12:44
MOT test number	179070889881
Result	✓ Passed
Next expiry date	2022-02-24
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT #16	2020-02-25 17:15
MOT test number	857972178266
Result	✓ Passed
Advice	Rear engine mount broken

MOT #15	2020-02-25 16:30
MOT test number	600602685043
Result	✗ Failed
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Rear engine mount broken
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2018-08-06 10:34
MOT test number	523701858308
Result	✓ Passed

MOT #13	2018-08-06 08:56
MOT test number	296614427904
Result	✗ Failed
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #12 2017-07-05 16:33

MOT test number 289705859704

Result ✓ Passed

MOT #11 2017-07-05 16:33

MOT test number 638197225753

Result ✗ Failed

Pass with rectification Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #10 2016-07-14 12:22

MOT test number 357408148550

Result ✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Emission too clean

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front side marker lamp inoperative

MOT #9 2015-07-14 14:03

MOT test number 847865895112

Result ✓ Passed

MOT #8 2014-07-08 10:27

MOT test number 536319484148

Result ✓ Passed

MOT #7 2013-07-12 13:26

MOT test number 266553693171

Result ✓ Passed



MOT #6	2013-07-12 13:26
MOT test number	665643493149
Result	✗ Failed
Pass with rectification	Offside Front All position lamps not working (1.1.A.3b)
Pass with rectification	Offside Front Headlamp aim too low (1.8)
Pass with rectification	Nearside Front All position lamps not working (1.1.A.3b)
Pass with rectification	Nearside Front Headlamp aim too high (1.8)

MOT #5	2012-07-02 15:54
MOT test number	207204982419
Result	✓ Passed

MOT #4	2011-07-11 09:53
MOT test number	256892491190
Result	✓ Passed

MOT #3	2010-07-01 16:38
MOT test number	470292880167
Result	✓ Passed

MOT #2	2009-07-08 10:55
MOT test number	281089889179
Result	✓ Passed

MOT #1	2008-07-14 15:57
MOT test number	321666598169
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	OW05BKX
Plate since	2024-03-29
Current registration	OW05BKX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-07-18
Last registration	2021-02-16
Complete history	See info



Registration #1	2005-07-18	19 mi
Registration #2	2008-07-14	35.699 mi
Registration #3	2009-07-08	46.851 mi
Registration #4	2010-07-01	55.529 mi
Registration #5	2011-07-11	63.195 mi
Registration #6	2012-07-02	69.891 mi
Registration #7	2013-07-12	80.181 mi
Registration #8	2014-07-08	85.416 mi
Registration #9	2015-07-14	90.718 mi
Registration #10	2016-07-08	95.999 mi
Registration #11	2017-07-08	101.280 mi
Registration #12	2018-07-08	106.561 mi
Registration #13	2019-07-08	111.842 mi
Registration #14	2020-07-08	117.123 mi
Registration #15	2021-02-16	122.404 mi
Registration #16	2021-02-16	127.685 mi
Registration #17	2021-02-16	132.966 mi
Registration #18	2021-02-16	138.247 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1833 mm
Height	1454 mm
Length	4850 mm
Wheel base	2835 mm
Kerb weight	1539 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	308092