



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	AGILA S
Colour	Black
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 2


Date	2021-07-11
Pictures	24
Listing price	<a href="#">View report</a>





**Video viewing**  
Book a video viewing with one of our team.  
See the vehicle from the comfort of your own home.


[Visit our website for more info](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-07-10
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-11-28
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	24
Total items failed	4

MOT #15 2023-11-16 09:05

MOT test number 949783856771

Result ✓ Passed

Next expiry date 2024-11-28

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14 2022-11-29 13:59

MOT test number 910490117442

Result ✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13 2021-09-11 11:35

MOT test number 154831748018

Result ✓ Passed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Front Brake pad(s) wearing thin N/S & O/S (1.1.13 (a) (ii))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened N/S & O/S (1.1.14 (a) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12**

2021-09-11 11:35

**MOT test number**

705123609966

**Result****✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened N/S & O/S (1.1.14 (a) (ii))**Pass with rectification** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin N/S & O/S (1.1.13 (a) (ii))**MOT #11**

2020-12-09 09:12

**MOT test number**

863564835422

**Result****✓ Passed****Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Nail in tyre**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10**

2019-07-25 10:51

**MOT test number**

973192743551

**Result****✓ Passed****MOT #9**

2018-07-26 13:28

**MOT test number**

893991482063

**Result****✓ Passed**

**MOT #8** 2018-07-26 07:53**MOT test number** 235340092091**Result** ✗ Failed

**DANGEROUS** Nearside Front Lower Steering linkage ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))

**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #7** 2017-09-11 13:49**MOT test number** 952750849856**Result** ✓ Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #6** 2017-09-11 13:49**MOT test number** 396424390363**Result** ✗ Failed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Pass with rectification** Nearside Headlamp aim too high (1.8)

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**Pass with rectification** Offside Headlamp aim too high (1.8)

**MOT #5** 2017-08-05 08:24**MOT test number** 758034369890**Result** ✓ Passed

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)



MOT #4	2016-08-15 10:40
MOT test number	829006855269
Result	✓ Passed
MOT #3	2015-08-22 09:12
MOT test number	753710854655
Result	✓ Passed
MOT #2	2014-08-23 11:01
MOT test number	359175234212
Result	✓ Passed
MOT #1	2014-08-23 11:01
MOT test number	907475234218
Result	✗ Failed
<div>Pass with rectification</div> Registration plate lamp not working (1.1.C.1d)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
28 November 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	28 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>FP11ENK</b>
Plate since	2019-06-29
Current registration	<b>FP11ENK</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-08-26
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2011-08-26	25 mi
Registration #2	2014-08-23	42.487 mi
Registration #3	2015-08-22	57.142 mi
Registration #4	2016-08-15	73.010 mi
Registration #5	2017-08-05	89.559 mi
Registration #6	2017-09-11	90.170 mi
Registration #7	2017-09-11	90.170 mi
Registration #8	2018-07-26	95.468 mi
Registration #9	2018-07-26	95.468 mi
Registration #10	2019-05-20	101.777 mi
Registration #11	2019-05-20	101.777 mi
Registration #12	2019-05-20	101.777 mi
Registration #13	2019-05-20	101.777 mi
Registration #14	2019-05-20	101.777 mi
Registration #15	2019-05-20	101.777 mi
Registration #16	2019-05-20	101.777 mi
Registration #17	2019-05-20	101.777 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1331429